

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference <i>VR-0017</i>	Date (YYYY-MM-DD) <i>2026-09-20</i>	Time <i>16:15</i>
Inspection site <i>Central depot</i>	Inspector name <i>Jamie Reed</i>	

2. VEHICLE IDENTIFICATION

Make <i>Suzuki</i>	Model <i>Swift</i>	Model year <i>2020</i>
Registration <i>TST 5218</i>	Colour <i>Blue</i>	Odometer (km) <i>63,819</i>
Fleet / vehicle reference <i>FLEET-0117</i>		

3. CONDITION CHECKLIST

Overall condition: ☒ Perfect ☐ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☒ None	☐ Scratch	☐ Dent	☐ Crack
☐ Broken part	☐ Tear	☐ Puncture	☐ Corrosion

Severity: ☒ None ☐ Minor ☐ Moderate ☐ Severe

4. FINDINGS & ACTION

Damage location <i>None</i>	Damage extent / dimensions <i>None observed.</i>
--------------------------------	---

Inspection notes / description:
Vehicle is in perfect condition on inspection.
All panels, glass, lights and fittings are intact.
No damage was recorded during this inspection.

Recommended action:
No repair required.

Driving restriction: ☒ None recorded ☐ Hold for repair

Inspector signature: *Jamie Reed*