

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0002

Date (YYYY-MM-DD)

2026-09-05

Time

10:30

Inspection site

West depot

Inspector name

Jamie Reed

2. VEHICLE IDENTIFICATION

Make

Volkswagen

Model

Golf

Model year

2024

Registration

TST 9917

Colour

White

Odometer (km)

46,070

Fleet / vehicle reference

FLEET-0102

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☐	☒
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☒ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Right rear door

Damage extent / dimensions

8 cm shallow dent; paint intact.

Inspection notes / description:

The right rear door has a shallow circular dent.

The door closes normally; no other damage seen.

Damage recorded in the component checklist.

Recommended action:

Arrange panel repair.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature: Jamie Reed