

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0003

Date (YYYY-MM-DD)
2026-09-06

Time
11:45

Inspection site
South depot

Inspector name
Robin Blake

2. VEHICLE IDENTIFICATION

Make
Ford

Model
Focus

Model year
2017

Registration
TST 1243

Colour
Grey

Odometer (km)
97,966

Fleet / vehicle reference
FLEET-0103

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☐	☒
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☒ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
Windscreen, lower left

Damage extent / dimensions
18 cm branching crack in the glass.

Inspection notes / description:

A crack runs from the lower left windscreen edge.
The crack branches toward the centre of the glass.
Damage recorded in the component checklist.

Recommended action:

Replace windscreen before driving.

Driving restriction:

☐ None recorded

☒ Hold for repair

Inspector signature:

Robin Blake