

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0005

Date (YYYY-MM-DD)

2026-09-08

Time

13:15

Inspection site

Central depot

Inspector name

Alex Morgan

2. VEHICLE IDENTIFICATION

Make

Skoda

Model

Octavia

Model year

2022

Registration

TST 1466

Colour

Red

Odometer (km)

59,171

Fleet / vehicle reference

FLEET-0105

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☐	☒
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☒ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Front bumper, left corner

Damage extent / dimensions

9 cm split through bumper cover.

Inspection notes / description:

The left corner of the front bumper cover is split.

The surrounding cover is scuffed.

Damage recorded in the component checklist.

Recommended action:

Repair or replace the bumper cover.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Alex Morgan

Page 1 of 1