

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0006

Date (YYYY-MM-DD)
2026-09-09

Time
14:30

Inspection site
West depot

Inspector name
Sam Taylor

2. VEHICLE IDENTIFICATION

Make
Renault

Model
Clio

Model year
2018

Registration
TST 3420

Colour
Green

Odometer (km)
46,240

Fleet / vehicle reference
FLEET-0106

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☐	☒
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☒ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☒ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
Rear bumper, centre

Damage extent / dimensions
22 cm scrape across painted surface.

Inspection notes / description:

A scrape crosses the centre of the rear bumper.

The cover remains attached and has no cracks.

Damage recorded in the component checklist.

Recommended action:

Refinish the scraped area.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Sam Taylor

Page 1 of 1