

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0007

Date (YYYY-MM-DD)
2026-09-10

Time
15:45

Inspection site
South depot

Inspector name
Jamie Reed

2. VEHICLE IDENTIFICATION

Make
Peugeot

Model
308

Model year
2017

Registration
TST 7554

Colour
Beige

Odometer (km)
88,524

Fleet / vehicle reference
FLEET-0107

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☐	☒
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☒ Broken part

☐ Scratch

☐ Tear

☐ Dent

☐ Puncture

☐ Crack

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
Left rear lamp

Damage extent / dimensions
Outer lens shattered; pieces missing.

Inspection notes / description:

The left rear lamp lens is shattered.

A section of the lens is missing.

Damage recorded in the component checklist.

Recommended action:

Replace rear lamp before driving.

Driving restriction:

☐ None recorded

☒ Hold for repair

Inspector signature:

Jamie Reed

Page 1 of 1