

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0009

Date (YYYY-MM-DD)

2026-09-12

Time

08:15

Inspection site

Central depot

Inspector name

Casey Ellis

2. VEHICLE IDENTIFICATION

Make

Kia

Model

Ceed

Model year

2022

Registration

TST 3788

Colour

Blue

Odometer (km)

79,503

Fleet / vehicle reference

FLEET-0109

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☐	☒

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☐ Crack

☐ Broken part

☒ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☒ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Driver seat cushion

Damage extent / dimensions

4 cm tear in seat upholstery.

Inspection notes / description:

A short tear is visible on the driver seat cushion.
The foam beneath the upholstery is exposed.
Damage recorded in the component checklist.

Recommended action:

Repair seat upholstery.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Casey Ellis