

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0010

Date (YYYY-MM-DD)

2026-09-13

Time

09:30

Inspection site

West depot

Inspector name

Alex Morgan

2. VEHICLE IDENTIFICATION

Make

Nissan

Model

Qashqai

Model year

2017

Registration

IST 5670

Colour

White

Odometer (km)

60,963

Fleet / vehicle reference

FLEET-0110

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☐	☒
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☒ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Left rear wheel arch

Damage extent / dimensions

6 cm patch of rust with flaking paint.

Inspection notes / description:

Rust is visible at the left rear wheel arch.

Paint is lifting around the affected area.

Damage recorded in the component checklist.

Recommended action:

Assess corrosion and repair the panel.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Alex Morgan