

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0011

Date (YYYY-MM-DD)
2026-09-14

Time
10:45

Inspection site
South depot

Inspector name
Sam Taylor

2. VEHICLE IDENTIFICATION

Make
Mazda

Model
3

Model year
2022

Registration
TST4931

Colour
Grey

Odometer (km)
74,236

Fleet / vehicle reference
FLEET-0111

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☐	☒
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☒ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
Bonnet, front edge

Damage extent / dimensions
Two dents, each about 5 cm wide.

Inspection notes / description:

Two dents are present along the front bonnet edge.

The paint surface is scratched around one dent.

Damage recorded in the component checklist.

Recommended action:

Repair and refinish the bonnet.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Sam Taylor

Page 1 of 1