

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0012

Date (YYYY-MM-DD)

2026-09-15

Time

11:00

Inspection site

North depot

Inspector name

Jamie Reed

2. VEHICLE IDENTIFICATION

Make

Opel

Model

Astra

Model year

2022

Registration

TST 8687

Colour

Black

Odometer (km)

92,408

Fleet / vehicle reference

FLEET-0112

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☐	☒
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☒ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☒ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Rear window

Damage extent / dimensions

3 cm star-shaped crack in rear glass.

Inspection notes / description:

A small star-shaped crack is visible in the rear glass.

No other glass damage was found.

Damage recorded in the component checklist.

Recommended action:

Have the damaged glass assessed and repaired.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Jamie Reed