

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0013

Date (YYYY-MM-DD)

2026-09-16

Time

12:15

Inspection site

Central depot

Inspector name

Robin Blake

2. VEHICLE IDENTIFICATION

Make

Volvo

Model

V40

Model year

2022

Registration

TST 1495

Colour

Red

Odometer (km)

93,534

Fleet / vehicle reference

FLEET-0113

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☐	☒
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☒ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☒ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Left mirror housing

Damage extent / dimensions

5 cm abrasion on painted housing.

Inspection notes / description:

The left mirror housing has a shallow abrasion.

The mirror glass and mounting are intact.

Damage recorded in the component checklist.

Recommended action:

Refinish the mirror housing.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Robin Blake