

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0014

Date (YYYY-MM-DD)

2026-09-17

Time

13:30

Inspection site

West depot

Inspector name

Casey Ellis

2. VEHICLE IDENTIFICATION

Make

Seat

Model

Leon

Model year

2022

Registration

TST 8669

Colour

Green

Odometer (km)

93,239

Fleet / vehicle reference

FLEET-0114

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☐	☒
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☒ Broken part

☐ Scratch

☐ Tear

☐ Dent

☐ Puncture

☐ Crack

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Right front headlamp

Damage extent / dimensions

Lens cracked; mounting tab broken.

Inspection notes / description:

The right headlamp lens is cracked.

One mounting tab is broken and the lamp is loose.

Damage recorded in the component checklist.

Recommended action:

Replace and secure headlamp before driving.

Driving restriction:

☐ None recorded

☒ Hold for repair

Inspector signature:

Casey Ellis

Page 1 of 1