

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference <i>VR-0015</i>	Date (YYYY-MM-DD) <i>2026-09-18</i>	Time <i>14:45</i>
Inspection site <i>South depot</i>	Inspector name <i>Alex Morgan</i>	

2. VEHICLE IDENTIFICATION

Make <i>Fiat</i>	Model <i>Tipo</i>	Model year <i>2021</i>
Registration <i>TST 8643</i>	Colour <i>Beige</i>	Odometer (km) <i>55,336</i>
Fleet / vehicle reference <i>FLEET-0115</i>		

3. CONDITION CHECKLIST

Overall condition: ☐ Perfect ☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☐	☒
Interior	☒	☐

Damage type (select one):

☐ None	☐ Scratch	☒ Dent	☐ Crack
☐ Broken part	☐ Tear	☐ Puncture	☐ Corrosion

Severity: ☐ None ☐ Minor ☒ Moderate ☐ Severe

4. FINDINGS & ACTION

Damage location <i>Left rear wheel rim</i>	Damage extent / dimensions <i>Rim edge bent inward by about 1 cm.</i>
---	--

Inspection notes / description:
The left rear wheel rim is bent at its outer edge.
The tyre remains inflated at inspection.
Damage recorded in the component checklist.

Recommended action:
Have wheel inspected before driving.

Driving restriction: ☐ None recorded ☒ Hold for repair

Inspector signature: *Alex Morgan*