

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0016

Date (YYYY-MM-DD)
2026-09-19

Time
15:00

Inspection site
North depot

Inspector name
Sam Taylor

2. VEHICLE IDENTIFICATION

Make
Dacia

Model
Duster

Model year
2019

Registration
TST 2903

Colour
Silver

Odometer (km)
19,083

Fleet / vehicle reference
FLEET-0116

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☐	☒

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☐ Crack

☒ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☒ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
Glove compartment lid

Damage extent / dimensions
Latch broken; lid will not stay closed.

Inspection notes / description:

The glove compartment latch is broken.

The lid drops open when released.

Damage recorded in the component checklist.

Recommended action:

Replace the latch and check closure.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Sam Taylor

Page 1 of 1