

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0017

Date (YYYY-MM-DD)
2026-09-20

Time
16:15

Inspection site
Central depot

Inspector name
Jamie Reed

2. VEHICLE IDENTIFICATION

Make
Suzuki

Model
Swift

Model year
2020

Registration
TST 5218

Colour
Blue

Odometer (km)
63,819

Fleet / vehicle reference
FLEET-0117

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☐	☒
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None

☐ Scratch

☒ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☐ Minor

☒ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
Rear bumper, right corner

Damage extent / dimensions
Indented cover with 10 cm paint scrape.

Inspection notes / description:

The right corner of the rear bumper is indented.

A paint scrape runs across the damaged area.

Damage recorded in the component checklist.

Recommended action:

Repair and refinish bumper cover.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Jamie Reed

Page 1 of 1