

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference	Date (YYYY-MM-DD)	Time
VR-0018	2026-09-21	08:30
Inspection site	Inspector name	
West depot	Robin Blake	

2. VEHICLE IDENTIFICATION

Make	Model	Model year
Citroen	C3	2021
Registration	Colour	Odometer (km)
TST9249	White	14,658
Fleet / vehicle reference		
FLEET-0118		

3. CONDITION CHECKLIST

Overall condition: ☐ Perfect ☒ Damage noted

Component inspected	No damage	Damage
Body panels	☐	☒
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None	☒ Scratch	☐ Dent	☐ Crack
☐ Broken part	☐ Tear	☐ Puncture	☐ Corrosion

Severity: ☐ None ☒ Minor ☐ Moderate ☐ Severe

4. FINDINGS & ACTION

Damage location	Damage extent / dimensions
Roof, rear section	Three scratches, 6 to 10 cm long.
Inspection notes / description:	
Three narrow scratches mark the rear roof section.	
Paint is affected; no dents were observed.	
Damage recorded in the component checklist.	
Recommended action:	
Polish or refinish the scratched area.	
Driving restriction:	☒ None recorded ☐ Hold for repair

Inspector signature: Robin Blake