

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference <i>VR-0019</i>	Date (YYYY-MM-DD) <i>2026-09-22</i>	Time <i>09:45</i>
Inspection site <i>South depot</i>	Inspector name <i>Casey Ellis</i>	

2. VEHICLE IDENTIFICATION

Make <i>Subaru</i>	Model <i>Impreza</i>	Model year <i>2017</i>
Registration <i>TST 5832</i>	Colour <i>Grey</i>	Odometer (km) <i>20,935</i>
Fleet / vehicle reference <i>FLEET-0119</i>		

3. CONDITION CHECKLIST

Overall condition: ☐ Perfect ☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☐	☒
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☐ None	☐ Scratch	☐ Dent	☐ Crack
☒ Broken part	☐ Tear	☐ Puncture	☐ Corrosion

Severity: ☐ None ☐ Minor ☒ Moderate ☐ Severe

4. FINDINGS & ACTION

Damage location <i>Front bumper, lower grille</i>	Damage extent / dimensions <i>Two grille slats broken; one missing.</i>
Inspection notes / description: <i>Two slats of the lower front grille are broken.</i> <i>One broken slat is missing from the opening.</i> <i>Damage recorded in the component checklist.</i>	
Recommended action: <i>Replace the lower grille insert.</i>	
Driving restriction: ☒ None recorded ☐ Hold for repair	
Inspector signature: <i>Casey Ellis</i>	Page 1 of 1