

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0020

Date (YYYY-MM-DD)

2026-09-23

Time

10:00

Inspection site

North depot

Inspector name

Alex Morgan

2. VEHICLE IDENTIFICATION

Make

BMW

Model

118i

Model year

2017

Registration

TST 9489

Colour

Black

Odometer (km)

65,510

Fleet / vehicle reference

FLEET-0120

3. CONDITION CHECKLIST

Overall condition:

☐ Perfect

☒ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☐	☒

Damage type (select one):

☐ None

☐ Scratch

☐ Dent

☒ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☐ None

☒ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

Centre console trim

Damage extent / dimensions

7 cm crack beside cup holder.

Inspection notes / description:

The trim beside the centre cup holder is cracked.

The crack extends across the upper trim surface.

Damage recorded in the component checklist.

Recommended action:

Replace damaged console trim.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Alex Morgan

Page 1 of 1