

Venue	LUM Fukuoka		Lot No.	3565	Score	4	Start price	¥0
Year	R1	Car Name	Corolla Axio		Grade			
Model	DAA-NKE165	Chassis number	NKE165-7225340		Color	Other	Gear	AT
Engine	1500cc	Mileage	82K km		Fuel		Car history	
Equipment	PS Record List Guarantee AC				Inspection	/00	Air conditioner	
Special note	Control number: 3241203-03565 5-seater First year: November 2019 Recycled: 9,470 yen Drive: 2WD Model designation: 17572 Classification: 0011 Deleted Mileage: 81,466 km Size: Compact							

開催No.	出品No.	会場名	評価点	内装評価点	修復歴
3241203	03565	LUM福岡	4	C	
引取先	福岡県福岡市東区蒲田4-368				

コアサポート

ロアサポート

バンパーホースメント

サイドメンバー突起部

クロスメンバー

サイドメンバー

インサイドパネル

フロア (キャブ床)

ピラーインナー

ダッシュパネル

センターフロア

ルーフパネル

サイドシルインナー

フロアサイドメンバー

セッパック (キャブ背)

ピラーインナー

トランクフロア

インサイドパネル

サイドメンバー

クロスメンバー

バックパネル

バンパーホースメント

下回り

フォグ 21

ヘッドライト 22

ウィンカー 23

アクターミラー 24

サイドウィンドウ

フロント 25

リア 26

荷室 27

テールランプ 28

バンパーランプ 29

6

7

8

9

10

11

12

13

14

15

16

17

18

AC

PS

保証書

記録簿

検付自賠責

31 フォグ

32 ヘッドライト

33 ウィンカー

34 アクターミラー

35 フロント

36 リア

37 荷室

38 テールランプ

39 バンパーランプ

※下記表の瑕疵の部位については画像を確認して下さい

部位名称	部位番号	瑕疵記号	部位名称	部位番号	瑕疵記号
ボンネット	8	A1			
Fバンパー	6	A1			
右Fフェンダー	14	A1			
右Fドア	15	A1			
右Rドア	16	A1			
左Rドア	4	A1			
左Fドア	3	A1			
Fバンパー	6	A1			
Rバンパー	13	A1			

特記事項

☐ ガラスヒビ 天張りスレ シートスレ・ヨレ

■グループBのA1/U1/C1は、クレーム対象外です。

グループ区分	押曲歪	交換歴	交換D	修復歴	修理D	線キス	凹み	腐食	凹傷	看板跡	ヒビ/加	交換跡	修理跡	塗装跡	指定塗装
B	D/U	X	DX/XD	W	DW/WD	A1-4	U1-4	C1-4	B1-4	P1-4	G/Z	XX	W1-3	P	指