

Venue	LUM Nagoya		Lot No.	4781	Score	4	Start price	¥0
Year	R1	Car Name	Corolla Axio		Grade			
Model	DAA-NKE165	Chassis number	NKE165-7224114		Color	Other	Gear	AT
Engine	1500cc	Mileage	75K km		Fuel		Car history	
Equipment	PS Record List Guarantee AC				Inspection	/00	Air conditioner	
Special note	Control number: 5241203-04781 5-seater First year: November 2019 Recycled: 9,470 yen Drive: 2WD Model designation: 17572 Classification: 0011 Deleted Mileage: 74,461 km Size: Compact							

開催 No.	出品 No.	会場名	評価点	内装評価点	修復歴
5241203	04781	LUM名古屋	4	C	
引取先	愛知県東海市名和町三番割中4番3				

AC
PS
保証書
記録簿
検付自賠責

21 フォグ
22 ヘッド
ライト
23 ウィン
カー
24 アウター
ミラー
25 フロント
26 リア
27 荷室
28 テール
ランプ
29 バンパー
ランプ

31 フォグ
32 ヘッド
ライト
33 ウィン
カー
34 アウター
ミラー
35 フロント
36 リア
37 荷室
38 テール
ランプ
39 バンパー
ランプ

サイドウィンドウ
フロント
リア
荷室

サイドウィンドウ
フロント
リア
荷室

※下記表の瑕疵の部位については画像を確認して下さい

[illegible]

特記事項															
<div> <div> <div></div> <div>ガラスヒビ</div> </div> <div>室内汚れ</div> <div>ホールキャップ傷</div> <div>エンジンルーム内サビ</div> </div>															
<div> <div>■グループBのA1／U1／C1は、クレーム対象外です。</div> </div>															
グループ区分	押曲重	交換歴	交換D	修復歴	修理D	線キズ	凹み	腐食	凹＆傷	看板跡	ヒビ/割	交換跡	修理跡	塗装跡	指定塗装
B	D/U	X	DX/XD	W	DW/WD	A1-4	U1-4	C1-4	B1-4	P1-4	G/Z	XX	W1-3	P	指

