

Prepared by: Bill DePrinzio

12:00 PM

44°F



Clear

Wind: 4 MPH | Precip: 0" | Hum: 36%%

4:00 PM

51°F



Clear


Wind: 4 MPH | Precip: 0" | Hum: 28%%

Qty: 1

Hours: 0

HTD: 0

the building for the brick installation. Completed all minor interior framing needs within the
es and returns in the soffit walls. Started Framing inside of the PJs space for the wall that



Qty: 2

Hours: 0

HTD: 0

mechanical room so we can repair the wall they were up against.


Qty: 3

Hours: 0

HTD: 0

opening on rear of the building.





Total: 12 workers | 0 hours

	N/A	No	Yes	Notes
		•		
		•		
		•		
		•		

—

●

●
