



caRya.krama

PROFESSIONAL VEHICLE INSPECTION SERVICES

VEHICLE INSPECTION REPORT

DATE
7 Apr 2026

REPORT ID
CK-INS-8MG8K-CK-6458437

INSPECTOR
Master Tech Z.K.



Vehicle Identification



Verified Profile

MAKE & MODEL Tata Sierra EV Premium	YEAR/MODEL 2025	CURRENT ODOMETER 12,500	TRANSMISSION AUTOMATIC
FUEL & ENGINE Electric	VIN NUMBER CK-CK-6458437	EXTERIOR COLOR Premium Metallic	INSPECTION GOAL STANDARD AUDIT



1. BODY & VISUAL INSPECTION



Paint Quality & Uniformity

Paint thickness is consistent across all major panels. No signs of major overspray.



Panel Alignment & Gaps



Glass & Mirrors

Minor rock chip on the passenger side windshield. Not currently spreading.



Rust & Corrosion Check

Zero rust found on undercarriage or door sills.



2. ENGINE BAY MECHANICS



No visible oil or coolant leaks



Hoses & Radiator Pipes intact



Engine Mounts

Showing minor wear but no excessive vibration in cabin.



Drive Belts Condition

Serpentine belt shows slight cracking; replacement recommended soon.



3. FLUIDS & LUBRICANTS

FLUID TYPE	CURRENT STATUS	ACTION REQUIRED
Engine Oil	Dark - Needs Service	Replace Oil & Filter
Coolant Antifreeze	Clean / Full	None
Brake Fluid	1% Moisture	None



4. BATTERY & ELECTRICAL SYSTEMS

RESTING VOLTAGE

12.6V

CHARGING
VOLTAGE

14.2V



HEALTH STATUS

Good / Acceptable

* Battery cranking amp test passed. Alternator charging sequence is perfectly within manufacturer parameters.



5. INTERIOR & CABIN QUALITY



Seats & Upholstery Condition

Leather is supple with no tears. Minimal bolter wear on driver's side.



Steering & Dashboard



Infotainment & Displays

Nav screen has a localized cluster of dead pixels on the bottom right.



AC & Climate Control

Blowing ice-cold within 30 seconds.



6. OBD II DIAGNOSTICS SCAN



SYSTEM SCAN INITIATED...

[08:42:12]	ENGINE ECU	NO FAULTS
[08:42:15]	TRANSMISSION TCM	NO FAULTS
[08:42:18]	ABS/ESP MODULE	NO FAULTS
[08:42:21]	AIRBAG SRS	1 STORED CODE

DIAGNOSTIC STATUS: **PASS**



7. DYNAMIC TEST DRIVE

COMPONENT	OBSERVATION	RATING
Engine Performance	Smooth delivery through RPM range.	PASS
Braking Stability	Minor shudder from front rotors at speed.	CAUTION



8. SERVICE & MAINTENANCE HISTORY



First service completed at 5,000 km – Tata Authorized Service Center



Battery health check completed at 10,000 km



9. VERIFIED SELLER INFORMATION

SELLER NAME

caRya.krama
Verified

ACCOUNT TYPE

Professional

MEMBER SINCE

2024

TRUST STATUS

PLATINUM

Professional Seller Audit: Verified Identity, Document Compliance, and Physical Inspection cleared.



OVERALL AUDIT VERDICT



Mechanically Sound

Vehicle passes all major powertrain and safety criteria.



Needs Attention

Brake shudder and minor fluids require addressing soon.



Recommendation

A solid purchase. Factor in minor maintenance costs.

IMMEDIATE ACTION ITEMS

- No immediate mechanical failures detected.
- Perform basic fluids audit in next 5,000 km.

LONG-TERM ADVISORY

- Minor scratch on rear bumper, polished during prep.
- Regular inspection recommended every 12 months.

INSPECTED BY

Master Tech Z. Khan

DATE COMPLETED

7 Apr 2026

INSPECTION CENTRE

Dubai HQ - Bay 4

OFFICIAL SIGNATURE

ZK. Inspections

DISCLAIMER: This inspection report constitutes an evaluation based on the technical and visual condition of the vehicle at the specific time of inspection. caRya.krama does not hold liability for future mechanical failures post-purchase. This document is digitally certified.

© 2026 CARYA.KRAMA DEALERSHIPS