

## STRUCTURAL SOUNDNESS CERTIFICATE

Correspondent of Catherine Academy of General & Technical Education at Vidya marg of Mulakuddu (GP) applied to inspect the building for which is proposed to apply for the purpose of recognition of the building of Catherine Academy of General & Technical Education and requested to issue the "Structural Soundness Certificate".

In this connection I visited the school building on date: 27.10.2021 and the concerned documents. In my inspection I observed the following facts.

The existing buildings was constructed with RCC Framed structure with isolated column and footing, the building consisting of three Buildings G+ 1<sup>st</sup> Floors only. All the RCC surfaces are well plastered along with brick masonry work. The maintenance of the building is good enough. The amenities like water supply and sanitation facilities are well maintained.

The buildings has G+ 1<sup>st</sup> floors.-2nos & Ground floor only – 1no.

- a. Ground floor has office rooms , store room, Library, Labs and class rooms, and 1<sup>st</sup> Floor has class Rooms and Laboratorys, meeting halls.

### Catherine Academy boundaries:-


East :- River Gostani

West :- Road

North :- Dry land

South :- PWD Road

So it is certified that the building of Catherine Academy of General & Technical Education at Vidya marg of Mulakuddu (GP) . Bheemunipatnam Mandal in Visakhapatnam District is in good condition and safe.



B.G.  
EXECUTIVE ENGINEER  
SUB DIVISION  
BHEEMUNIPATNAM  
11/3/2022

*S. S. Srinivas* 11/03/2022  
Mandal Engineering Officer  
Mandal Praja Parishad  
Bheemunipatnam, Visakh Dist.