


e11 - Comments Sheet

Project Name: 1320-Renovation of villa at skhral temara,Rabat,Morocco.

Submittal Description	T&C Inspection of B1 kitchen Cooking Gas works				
Submittal Type	T&C Inspection Request				
Reference No	TC-PLOT A-B1-GAS-36	Rev.	0	Date	28.Feb.24
Status Code	C-Revised and resubmit				

Inspection comments to comply:

1. Gas supplier to provide full training for end-user FM team for maintenance and operations
2. All equipment shall be labeled in both english and arabic languages.
3. All valves to have supply directions (arrows) to kitchen, ovens, burners, etc.
4. All gas main valves shall be tagged (Identification labels) to be provided in English and Arabic language
5. Deep cleaning to be done for all the equipment's
6. Burners are not auto ignite, lighters to be provided
7. complete training to be provided to end user, FM team for operations and maintenance
8. Gas sensor provided inside panel to be marked and cleaned and labeled
9. Gas Cylinders to be filled fully and operational at the time of handover
10. Danger and non smoking signs to be provided.
11. Keys for main valve to be provided
12. **ventilation (Makeup & exhaust Air) to be provided for hoods and gap to be completed in hoods with additional filter**
13. Hood oil collector should be marked for cleaning, and the same to be explained to the Fm team, end user
14. Schematic diagram and sequence of operations shall be provided inside the kitchen room with framing and layout shall be in both languages indicating the main shut off valves.
15. **1 vertical freezer is damaged to be replaced as explained at site.**
16. Provided with operation manual (O&M) and submit updated as built drawings;
17. Comply with all above comments at the earliest.

Name: Eng. Giyassudin	Sr.MEP Engineer	Signature	
-----------------------	-----------------	-----------	---