

UAUC Capture Report

Audit ID: MABP-6 | Project: MABP | 9/7/2026, 1:47:20 pm

2

Safety Issues Found

2

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Accumulation of debris and dirt on the equipment, which may affect its functionality and safety.	Equipment malfunction due to debris accumulation.
Visible wear and tear on structural components, potentially compromising stability.	Structural failure or instability leading to falling objects or collapse.

AI Recommendations

- Clean and maintain equipment regularly to ensure proper functionality.
- Inspect structural components for wear and tear and replace damaged parts promptly.

Analyzed Image

