

UAUC Capture Report

Audit ID: MPSB-29 | Project: MPSB | 7/9/2026, 11:19:57 AM

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker at height without visible fall protection	Fall from height
Loose materials on the platform	Trip and fall due to loose materials
Worker using mobile phone in a construction zone	Distraction leading to accidents

AI Recommendations

- Ensure workers at height use proper fall protection equipment.
- Remove loose materials from the platform to prevent tripping hazards.
- Prohibit mobile phone usage in active construction zones.

Analyzed Image

