

UAUC Capture Report

Audit ID: MSBP_Sarai Ghat-4 | Project: MSBP_Sarai Ghat | 12/6/2026, 10:04:16 am

3

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Worker squatting in an unsafe posture on an elevated structure without visible fall protection.	Worker may lose balance and fall from the elevated structure, leading to serious injury.
Uneven and potentially unstable surface where the squatting worker is positioned.	Workers may trip over loose material or debris, causing minor to severe injuries.
Loose material and debris on the floor near workers, creating trip hazards.	high

AI Recommendations

- Ensure all workers on elevated structures use proper fall protection equipment such as harnesses.
- Inspect and secure the surface of elevated structures to ensure stability and safety.
- Clear loose material and debris from the work area to eliminate trip hazards.

Analyzed Image

