

Compliance Audit Report

Audit ID: MSBP_Sarai Ghat-41 | Project: MSBP_Sarai Ghat | 6/3/2026, 7:56:43 AM

2

Safety Issues Found

3

Recommendations

Detected Safety Issues

Safety Issue	Potential Risk
Wet and slippery floor in the work area.	Workers may slip and fall due to the wet and slippery floor.
Debris and loose materials scattered on the floor.	Tripping hazards due to debris and loose materials on the floor.

AI Recommendations

- Clean and dry the floor to eliminate the wet and slippery conditions.
- Remove debris and loose materials from the work area to prevent tripping hazards.
- Ensure proper housekeeping practices are followed regularly.

Analyzed Image

