

HRL FM Inspection App & Reporting

OVERVIEW

DATA CONNECTIONS & REPORT RELATIONSHIPS

Inspection App: Overall Room Condition (data collection) [*supplies*] **Report: Overall Room Condition Table (view)**





Overall Room Condition Ratings

DateCreated	Unit	Reason	Room	Rating	Room Cond Notes	SRzID
5/2/2022 10:33:25 AM	488Farrish-5	Pre-Move Out	BathRoom	Fair		190
5/2/2022 10:31:40 AM	488Farrish-5	Pre-Move Out	Bedroom 1	Good		190
5/2/2022 10:34:36 AM	488Farrish-5	Pre-Move Out	Kitchen	Good		190
5/2/2022 10:33:53 AM	488Farrish-5	Pre-Move Out	LivingRoom	Good		190
5/2/2022 9:32:18 AM	117Mimosa-B1	Post-Move Out	BathRoom	Good		189
5/2/2022 9:30:52 AM	117Mimosa-B1	Post-Move Out	Bedroom 1	Good	Mattress is missing and needs a replacement	189
5/2/2022 9:29:37 AM	117Mimosa-B1	Post-Move Out	Kitchen	Good		189
5/2/2022 9:28:25 AM	117Mimosa-B1	Post-Move Out	LivingRoom	Good		189
4/29/2022 2:14:13 PM	117Mimosa-B2	Pre-Move In	BathRoom	Good		188
4/29/2022 2:13:33 PM	117Mimosa-B2	Pre-Move In	Bedroom 1	Good		188
4/29/2022 2:10:36 PM	117Mimosa-B2	Pre-Move In	Kitchen	Good		188
4/29/2022 2:10:03 PM	117Mimosa-B2	Pre-Move In	LivingRoom	Good		188
4/26/2022 11:13:30 AM	422Farrish-B27	Pre-Move In	BathRoom	Good		187
4/26/2022 11:14:46 AM	422Farrish-B27	Pre-Move In	Bedroom 3	Good		187

Inspection App: Finalized Inspection (collect data) [*supplies*] **Report: Final Inspection Notes (view)**





Final Inspection Notes

Unit	Reason	Unit Result	InspNote	SRzID
488Farrish-5	Pre-Move Out	Good		190
117Mimosa-B1	Post-Move Out	Good		189
117Mimosa-B2	Pre-Move In	Good		188
422Farrish-B27	Pre-Move In	Good	Tub needs cleaning	187
117Mimosa-B2	Post-Move Out	Good		183
476Farrish-8	Pre-Move Out	Good		182
476Farrish-4	Follow Up	Good	Tub has been resurfaced	181
285Peyton-B19	Pre-Move Out	Good		178
278Peyton-5	By Request	Follow Up Needed	Tub needs to be scheduled to be resurfaced or to be resurfaced during a Full PFO.	177
287Peyton-8	Pre-Move In	Good		176
433Seymour-4	Pre-Move In	Good		175
412Seymour-2	Post-Move Out	Good		151
117Mimosa-B3	Post-Move Out	Good		150

Inspection App: Finalize Inspection

Default state:

Doing nothing (even skipping this section), the Inspection reports as Good in the “Unit Result” report column.

Consideration:

If a Follow Up Inspection is needed, checking the flag, and adding a note will help with visibility.

Future Workflow Automation: (Ex. automatic scheduling or auto-email notifications could be added to this data flag.

Report: Example of filtering on UNIT RESULTS = “Follow Up Needed”



Inspection App: Fixture Condition (data collection per room) [*supplies*] **Report: Fixture Condition Report (views)**

If fixtures do not require an ACTION, check "All Fixtures in Good Condition."

Then Submit will save that selection to the database.

NOTE: Floor or Furniture allows one to save a condition rating ***on those two items only.*** The rating info can be used for future renovation considerations.

If Damaged: requires a note to be submitted. It should be flagged for Follow Up as well.

The information collected in each room is reported in the Fixture Condition Report.

The table provides a variety of filters and sorting tools to view the most import action items.

Clicking TRUE on the "All-Good" filter removes all rows that do not have any Action items or condition ratings (Good, Fair, Poor).



DateCreated	Unit	Room	AllGood	Fixture	Condition/Action	Condition Notes	Damage Notes	SRzID
5/2/2022 10:34:00 AM	488Farrish-5	Kitchen	True					190
5/2/2022 10:33:00 AM	488Farrish-5	LivingRoom	True					190
5/2/2022 10:33:00 AM	488Farrish-5	BathRoom	False	Floors	Clean			190
5/2/2022 10:33:00 AM	488Farrish-5	BathRoom	False	Shower/Tub	Clean			190
5/2/2022 9:28:00 AM	117Mimosa-B1	LivingRoom	True					189
5/2/2022 9:29:00 AM	117Mimosa-B1	Kitchen	False	Countertop	Clean			189
5/2/2022 9:32:00 AM	117Mimosa-B1	BathRoom	False	Mirror/MedCabinet	Clean			189
5/2/2022 9:29:00 AM	117Mimosa-B1	Kitchen	False	Smart Burner	Replac			189
4/29/2022 2:14:00 PM	117Mimosa-B2	BathRoom	True					188
4/29/2022 2:10:00 PM	117Mimosa-B2	Kitchen	True					188
4/29/2022 2:10:00 PM	117Mimosa-B2	LivingRoom	True					188
4/26/2022 11:12:37 AM	422Farrish-B27	Hallway	True					187
4/26/2022 11:11:57 AM	422Farrish-B27	Kitchen	True					187
4/26/2022 11:11:14 AM	422Farrish-B27	LivingRoom	True					187
4/26/2022 11:13:35 AM	422Farrish-B27	BathRoom	False	Shower/Tub	Clean			187
4/22/2022 9:46:53 AM	117Mimosa-B2	BathRoom	False	Bath Sink/Vanity	Clean			183
4/22/2022 9:42:40 AM	117Mimosa-B2	LivingRoom	False	Blinds	Repair			183
4/22/2022 9:44:09 AM	117Mimosa-B2	Kitchen	False	Countertop	Repair			183
4/22/2022 9:46:48 AM	117Mimosa-B2	BathRoom	False	Exhaust Fan	Clean			183
4/22/2022 9:44:14 AM	117Mimosa-B2	Kitchen	False	Kitchen Sink	Clean			183
4/22/2022 9:46:57 AM	117Mimosa-B2	BathRoom	False	Shower/Tub	Clean			183
4/22/2022 9:44:21 AM	117Mimosa-B2	Kitchen	False	Stove	Clean			183
4/22/2022 9:47:01 AM	117Mimosa-B2	BathRoom	False	Toilet	Clean			183
4/22/2022 9:46:42 AM	117Mimosa-B2	BathRoom	False	Walls	Clean			183
4/22/2022 9:46:45 AM	117Mimosa-B2	BathRoom	False	Walls	Clean			183
4/22/2022 9:42:29 AM	117Mimosa-B2	LivingRoom	False	Walls	Clean			183
4/22/2022 9:42:26 AM	117Mimosa-B2	LivingRoom	False	Walls	New Paint			183
4/19/2022 2:22:02 PM	476Farrish-8	BathRoom	True					182
4/19/2022 2:18:47 PM	476Farrish-8	LivingRoom	True					182
4/19/2022 2:20:08 PM	476Farrish-8	Kitchen	False	Countertop	Clean			182
4/19/2022 2:19:55 PM	476Farrish-8	Kitchen	False	Floors	Clean			182
4/19/2022 2:20:02 PM	476Farrish-8	Kitchen	False	Kitchen Sink	Clean			182
4/19/2022 2:15:19 PM	476Farrish-4	BathRoom	True					181
4/19/2022 2:08:16 PM	499Seymour-1	BathRoom	True					179
4/19/2022 1:41:52 PM	285Peyton-B19	Hallway	True					178



Inventory can be added or view using the buttons to right. (All Rooms)

All inventory should currently be loaded.

Furniture

Kitchen

Bathroom

Bedrooms

[Demo App]