



AssetProof AIRPROPERTY

SNAG & MAINTENANCE REPORT

Snag & Maintenance Report (Sample)

Issues spotted on capture, with advice and likely local costs. An anonymised example.

PROPERTY

Sea-facing apartment · Sea Point
promenade (sample)

TYPE

Short-term rental — anonymised sample



AssetProof

Turning physical assets into structured, defensible digital evidence.

www.AssetProofSolutions.com · WhatsApp +27 82 221 4313 · Team@WirelessAlert.co.za



1 What we noted

The items worth attention from the capture. Costs are conservative local estimates for budgeting — obtain quotes before booking work. Severity reflects urgency, not alarm.

2 Needs attention

ITEM / LOCATION	SEVERITY	FINDING & RECOMMENDED ACTION	EST. COST (R)
Under-sink plumbing — kitchen	MEDIUM	Surface corrosion on the trap & fittings (functional, not leaking). Have a plumber replace or treat & monitor.	350 – 900
Oven trays — kitchen	LOW	Enamel worn on the baking trays. Replace with two new trays.	200 – 500
Cutlery — kitchen	LOW	Part set: mixed handles, short on teaspoons. Top up to a full matched canteen.	400 – 900
Estimated total			R 950 – 2,300

3 How to read this

How to read this

Severity is about urgency, not alarm. Safety-critical items (electrical, gas, water ingress, structural) would be flagged High or Critical with a 'use a professional' note. Re-capture over time tracks whether anything changes.

Anonymised sample. Costs are conservative local estimates in ZAR for budgeting, not quotes.