

FIXTURES & CONTENTS SCHEDULE

Fixtures & Contents Schedule

What belongs to the building, and what is loose — separated, so a handover can be signed

PROPERTY

Two-bedroom house, City Bowl, Cape Town

REFERENCE

SAMPLE-B

INSPECTION DATE

20 July 2026

AREAS RECORDED

15



1 What this schedule is

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

The letting schedule. It separates what is **part of the building** — fitted joinery, sanitaryware, flooring, gates, the braai, the pool shell — from what is **loose and removable**: the furniture, the appliances, the crockery and the tools. That distinction is the one that matters at handover and at the end of a tenancy, because the two are treated differently by every landlord, every tenant and every insurer.

58 entries are recorded as fixtures and fittings; 300 are recorded as contents.

2 At a glance

58 FIXTURES & FITTINGS	300 LOOSE CONTENTS	15 AREAS	R1.46m REPLACEMENT, EXPECTED
----------------------------------	------------------------------	--------------------	---

3 Fixtures and fittings — part of the building

Recorded for condition. These do not leave with the tenant and, where they form part of the building fabric, no separate replacement figure is carried.

4 Exterior & entrance

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Street-frontage boundary wall, sage-green painted plaster/render	1	GOOD	Render intact and evenly painted, no cracks or stains visible from street distance; wall paint appears slightly scuffed near the sliding gate track	
Driveway paving - large square exposed-aggregate/textured concrete pavers laid in a grid	1	POOR	Paving stones heavily stained with dark patches and algae-type staining throughout, with marked colour variation and uneven weathering between squares	Plate 001
Concrete steps from the paved driveway area down to the lawn - three risers, grooved anti-slip nosing strips, with a wood-look tiled bench/step ledge at the base	1	FAIR	Dark algae/moisture staining across the steps, hairline crack in the concrete riser near the planter, steps stained and worn	Plate 002, Plate 001
Low sage-green rendered retaining wall / raised planter ledge cast into the boundary wall alongside the driveway	1	FAIR	Surface staining on the retaining wall render	Plate 002, Plate 001

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Front garden bed and lawn - aloe/agave succulents, a large aeonium-type plant with dark maroon rosettes on bare woody stems, and potted succulents on a low stone/brick planter	1	FAIR	Patchy/thin lawn areas; planted material otherwise in leaf	
Side passage exterior wall, sage/pale-green painted plaster	1	FAIR	Visible plaster/render texture patchiness across the wall surface	Plate 003
Corrugated metal roof over the lean-to/shed structure at the far end of the side passage	1	FAIR	Sheeting in place; surface condition not assessable at the distance and angle available	Plate 003
Flat rooftop terrace - floor coated in grey waterproofing paint beneath an overhanging grey-painted concrete slab	1	POOR	Dark damp-like staining with moss/algae discolouration on the unfinished concrete wall section, and a rough, unpainted/unfinished concrete patch contrasting with the surrounding painted walls	Plate 004

5 Pool courtyard

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Small octagonal plunge pool - shell, submerged steps and water	1	POOR	Pool water severely green, murky and opaque, an algae bloom; dark sediment/algae buildup visible on the submerged steps and pool floor; dark algae staining on the pool walls. Water was not clear at any point in the record	Plate 005, Plate 006, Plate 007, Plate 008, Plate 009, Plate 010, Plate 011
Pool coping and paved surround - white-painted concrete coping with white stone/tile paving	1	POOR	Hairline cracks visible in the white pool-surround paving, grime and dark staining on several paving stones, and water-staining discolouration on the white coping	Plate 007, Plate 009, Plate 010, Plate 011
Artificial turf (astroturf) ground covering to the pool courtyard	1	FAIR	Turf laid flat and complete; dry pine needles and loose debris scattered across the surface at inspection	Plate 005, Plate 006, Plate 008, Plate 012, Plate 009, Plate 013, Plate 014
White-painted concrete steps leading up from the courtyard to the side door	1	GOOD	Three to four risers, edges intact, no cracking noted	Plate 005, Plate 006, Plate 008, Plate 013, Plate 014
Courtyard boundary walls - sage-green painted render enclosing two sides, with small drain/weep holes near the base	1	GOOD	Render intact and evenly painted, no cracks or staining recorded on these wall faces	Plate 005, Plate 006, Plate 008, Plate 012

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
White-painted low step/ platform running along the base of the house in the courtyard	1	FAIR	Hairline crack visible in the paved step/ platform near the water butt	Plate 005, Plate 008
Courtyard-facing window glazing behind the security bars	1	POOR	The window glass is heavily covered in dozens of dust and grime specks across the pane, giving a hazy appearance and materially reducing visibility through it	Plate 011
Tiled pitched roof edge with white fascia and gutter trim above the courtyard	1	GOOD	Tiles and fascia trim in place, no sagging or missing sections visible	Plate 009

6 Outdoor courtyard & braai

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Built-in outdoor kitchen counter - sage-green painted masonry with a white/pale grey countertop	1	FAIR	Counter and top intact; light scuff/dirt mark on the painted pillar to the left of the braai opening	Plate 017, Plate 018, Plate 019
Braai chimney/flue - tall rectangular rendered stack with a dark metal cap and small finial above the patio roof	1	GOOD	Render, cap and finial intact, no cracking visible	Plate 018
Covered patio roof (flat roof) with grey square structural support columns	1	GOOD	Roof and columns intact, no cracking or water marking visible	Plate 018
Patio flooring - wood-look ceramic/ porcelain plank tile in a brown tone with a raised step	1	GOOD	Consistent plank pattern with intact grout lines, no cracks or lifted tiles visible; tiles appeared wet/reflective near the doorway at inspection	Plate 020, Plate 021, Plate 022, Plate 023
Built-in outdoor kitchenette wall unit with two recessed niches/shelves, sage-green painted face	1	FAIR	The interiors of the wall niches are left as bare, unpainted grey cement/plaster, an unfinished finish contrasting with the painted sage-green facing	Plate 026
White wooden slatted balustrade/ railing at the patio edge	1	GOOD	Slats and rail intact, paint sound	Plate 021
Built-in alcove with a light-coloured bench/shelf seat in the patio nook, with white cornice moulding at the ceiling	1	GOOD	Bench, alcove and cornice intact, no cracking or staining visible	Plate 027
Steps from the lawn up to the covered patio - grey concrete paver steps with dark-stained wooden step edging	1	POOR	The wooden step edging below the deck is weathered, discoloured and algae- stained with heavy dark patches and grain wear; the concrete paver steps are stained and worn with a rough surface texture	Plate 018

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Grey paving stepping stones set across the rear lawn leading to the patio	1	FAIR	Stones in place; surrounding lawn muddy and worn between them	Plate 018
Rear garden paved patio - large square textured concrete slabs	1	FAIR	Dirt and staining in the slab grout lines, with further staining across the paved tiles	
Rear and side garden lawn	1	POOR	Patchy, weedy and unmown, with bare soil and muddy patches and thin grass throughout	
Garden beds and planting to the rear and side yard - succulents, agave, aloes, cacti including prickly pear, small ornamental trees and three bare deciduous trees, edged with a wooden timber border	1	GOOD	Planting established and in leaf; deciduous trees bare at the time of inspection (winter)	
Light grey-blue rendered boundary and low retaining wall to the side/back yard	1	FAIR	Visible horizontal crack or construction-joint line running through the render partway up the low wall	
Grey horizontal-slat timber-style fence/wall to the rear of the side yard	1	GOOD	Slats and posts intact, no leaning or rot visible	
Grey precast concrete panel boundary/screen wall to the rear garden, with electric fence wires along the top	1	GOOD	Panels seated and upright, no cracking or displacement visible	Plate 018
Patio walls and pillars - sage-green painted render	1	FAIR	Light scuff/dirt mark on the pillar beside the braai opening; render otherwise sound and evenly painted	Plate 017, Plate 023, Plate 019

7 Garage

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Garage floor - bare grey concrete/screed	1	POOR	Various stains and scuff marks across the floor, finish worn and patchy in places, multiple dark stains/patches, and a crack/joint line running across the concrete near the garage door threshold	Plate 031, Plate 032, Plate 033
Garage internal walls - taupe/beige and grey painted plaster	1	FAIR	Diagonal hairline crack running down from the corner near floor level, and scuff/dirt marks along the base of the wall	Plate 031, Plate 030, Plate 034
Wooden bamboo-look board/shelf panel wedged between the laundry appliances	1	GOOD	Board intact	Plate 038

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Concrete drainage channel with metal grate running along the base of the wall at the garage threshold	1	FAIR	Channel and grate in place; slight water staining at the base of the wall near the garage entrance, and moss/algae staining on the adjoining stone steps and paving	Plate 028

8 Laundry / utility & storage

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Timber-topped laundry counter/shelf spanning the washer and dryer, with a black plastic wall-mount bracket fixed to the wall behind	1	FAIR	General utility-area wear; no structural damage observed	Plate 039, Plate 040, Plate 043
Utility recess joinery - white floating shelf/wall cabinet unit over a white appliance-height countertop, with a loose thin metal/plastic trim strip lying on the counter	1	FAIR	Small dark speckled marks/residue on the lower countertop surface left of centre; a trim strip is detached and lying loose on the counter	Plate 044, Plate 041
Switched wall socket outlet and a second switch/isolator box in the utility recess	2	GOOD	No damage observed	Plate 044
Electrical distribution board - white cover panel with two rows of circuit breakers labelled LIGHTS, LIGHTS, LIGHTS, GEYSER, TIMER, STOVE, EARTH LEAKAGE, PLUGS x5 (top row) and MAIN SWITCH, EARTH LEAKAGE, POOL, PLUGS x3, SHAVER (bottom row); Riken RKH-225 breakers; bilingual English/Afrikaans WARNING/WAARSKUWING label	1	GOOD	Board and labelling intact, surrounding wall paint sound with no cracks or damage	
Prepaid electricity metering installation - ECON keypad unit (numeric keypad 1-9, 0, CLR) with LCD display reading 847, PT1 three-phase breaker switches, and a Plessey meter panel marked '800 imp/kWh 20(80)A 3 x 230/400V 50Hz', serial 06 6354 6540 1, with bilingual WARNING/ISILUMKISO anti-tamper label	1	GOOD	Meter and labelling intact, no tamper damage observed	
Alarm and security installation in the service cupboard - beige/cream metal alarm control box with orange and black wiring, a blue circuit board/relay module, a white 'FIDELITY ADT' module with green circuit board and LED indicators, and a vented wall-mounted device plugged into a red-covered socket	1	FAIR	Exposed orange/black wiring around the alarm control box, not fully enclosed	Plate 045
Built-in service cupboard housing the alarm equipment - white cabinet door on chrome hinges, plain white walls and ceiling	1	FAIR	Unpainted/unfinished timber strip visible at the top of the door lining opening; otherwise sound	Plate 045

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Built-in white storage cupboard with three shelves and brown/bronze-toned hinges	1	GOOD	Plain white laminate shelves, no visible damage	Plate 046
Large white melamine built-in storage cupboard system with multiple full-height compartments, doors, and a section of small square/rectangular cubby shelving	1	FAIR	General scuffing and wear on the cabinet interior surfaces; no major structural damage observed	Plate 047, Plate 041
Empty built-in cabinet with two shelf compartments, cream/beige interior, metal hinges	1	FAIR	Multiple small dark specks/marks scattered across the interior back and side walls and shelf (at least four visible in one view, at least six across two shelf levels in another); possibly dirt or insect debris	Plate 048, Plate 049
Built-in white melamine cupboard compartment with sloped ceiling panel following the roofline, soft-close hinge and a small round fitting at the top of the sloped panel	1	POOR	Brownish/tan smear stains across the centre of the sloped white back panel; scattered small dark speckled marks (dirt or possible mould) on the left interior panel; general grime/dust build-up on interior surfaces	Plate 050
Utility/garage floor - bare grey concrete screed	1	POOR	Unfinished bare concrete with dark staining and marks across the surface	Plate 040, Plate 047

9 Kitchen

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Fitted overhead wall cabinets, white gloss, including two hydraulic lift-up (flip-up) units, one glass-fronted, with white internal shelving	1	GOOD	Interiors clean and undamaged; small dark mark/dot on one cabinet interior side wall (possibly a screw hole or blemish)	Plate 051, Plate 052, Plate 053, Plate 054, Plate 055
Fitted base cabinets and drawer units, white laminate carcass and fronts, dark brown/black kickboard strip	1	GOOD	Drawer fronts and carcass show no visible damage; thin exposed particleboard/MDF strip along the front shelf edge where laminate meets underside	Plate 051, Plate 056, Plate 057, Plate 058, Plate 059
Under-sink base cabinet, white melamine interior with chrome hinges, two shelf levels	1	FAIR	Dark smudge/mark on the white laminate shelf surface; general wear consistent with under-sink storage	Plate 060
Perimeter worktop, cream/white speckled quartz-look engineered stone, glossy finish, with matching light-grey upstand to wall join	1	GOOD	Smooth and largely unmarked; small dark mark on the countertop near the wall junction (chip, stain or shadow - cause unclear)	Plate 051, Plate 061, Plate 059

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Kitchen island / breakfast-bar worktop, two-tone butcher-block timber (pale yellow-toned section meeting darker reddish-brown section), on timber supports and black metal L-brackets	1	FAIR	Clear colour/tone mismatch seam where the pale wood section meets the darker reddish-brown section beside and behind the hob	Plate 062, Plate 058, Plate 063, Plate 064, Plate 065
Solid pine plank flooring, knotty honey-toned boards, with metal transition/threshold strip at the change of floor finish	1	FAIR	Glossy sheen with scuff/wear marks in the high-traffic area near the cabinets; floorboard gap/seam visible near the threshold; metal transition strip slightly raised/uneven where it meets the timber	Plate 058, Plate 059
Recessed ceiling downlights to kitchen (sloped/pitched ceiling section near window)	1	GOOD	No defects observed	Plate 051
Window security guard / burglar bars to kitchen window (seen externally)	1	GOOD	No defects observed	Plate 051
White wall socket outlets, South African 3-round-pin type, including one double socket; one outlet fitted with a marked cover	4	GOOD	No damage observed	Plate 051, Plate 056, Plate 067, Plate 054
Wall-mounted device labelled 'EMERGENCY' (panic button / emergency switch)	1	GOOD	No damage observed	Plate 066

10 Contents — loose and removable

Recorded for condition, quantity and replacement value. This is the schedule a tenant signs against at move-in and is measured against at move-out.

11 Exterior & entrance

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Electric fence system to boundary wall - multiple black strand wires on white/black insulator standoff brackets, running the full length of the wall, with a small yellow warning sign	1	GOOD	Wires taut and standoffs in place; no broken strands or leaning brackets visible. Yellow warning sign text not legible at inspection resolution	
White satellite dish mounted on roof pillar	1	GOOD	Dish and arm intact, no visible corrosion at this distance	
Motorised sliding driveway gate - dark-brown horizontal wood-slat panels in a galvanised steel surround, four bays divided by galvanised vertical posts, running on a ground track	1	FAIR	The top-left bay is a distinctly lighter, newer-looking wood tone than the uniformly dark-stained panels beside it, suggesting a repaired or replaced panel; gate surface shows scuffed/worn patina	

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Sliding gate motor unit, mounted at the base of the gate at its right end	1	GOOD	Housing in place, no damage or corrosion visible	
Driveway planter display - terracotta and plastic pots holding aeonium/echeveria-type succulents and aloes, with driftwood/root decor pieces	1	GOOD	Plants in leaf, pots intact	
Prickly-pear (Opuntia) cactus and a small green succulent in metal/ceramic pots on the low wall beside the steps, with loose driftwood pieces set in beside them	2	GOOD	Plants healthy, pots intact	Plate 002
Small teal-blue plant pots with seedlings, placed on the edges of the concrete steps	2	GOOD	Pots intact, seedlings in leaf	Plate 001
Teal-green wheelie-bin-style container standing beside the front garden planter	1	GOOD	Body intact, no damage visible	
Dark grey plastic wheelie bins standing on the driveway paving, the right-hand one hand-painted in white lettering 'the property [locality redacted]'	2	GOOD	Bodies and lids intact, no cracks visible	
Green plastic cylindrical rainwater/water storage tank standing in the side passage against the wall	1	GOOD	Tank body intact, no splits or leaks visible	Plate 003
White PVC downpipes and surface plumbing running down the side passage wall	1	GOOD	Pipework in place and secured, no visible breaks	Plate 003
Black wrought-iron side gate in the side passage	1	GOOD	Gate in place, no rust or damage noted	Plate 003
Small white wall-mounted sensor/box on the side passage wall	1	GOOD	Housing intact, no damage visible	Plate 003
Roof-level pipe manifold - cluster of blue and copper-coloured pipes with valves and fittings mounted at the ceiling/wall junction under the overhang	1	GOOD	Pipework and valves in place, no leaks or corrosion visible	Plate 004
Black wall-mounted light fixture and adjacent electrical junction/inspection cover on the roof terrace	1	GOOD	Fixture and cover in place, no damage visible	Plate 004
Pale-green access hatch/door in the roof-terrace wall, standing open over a recessed water meter or valve assembly	1	GOOD	Hatch and recessed assembly intact; hatch found standing open at inspection	Plate 004

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Folding clothes-drying rack standing on the roof terrace	1	GOOD	Surround intact, no damage visible	Plate 004
Washing-line wires strung across the roof terrace, with a TV aerial/satellite mount alongside	1	GOOD	Lines in place, no sagging or breaks visible	Plate 004
Black burglar bars to the window in the cream/beige wall at roof-terrace level	1	GOOD	Bars secure in the surround, no rust noted	Plate 004
Boundary outlook from the roof terrace – mature planting and rooflines beyond the boundary wall, recorded for context	1	GOOD	No defect observed to anything within the property boundary	

12 Pool courtyard

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
White plastic sun-lounger chairs with adjustable slatted backrests, one fitted with caster wheels on its front legs	2	FAIR	Scuff marks and light dirt visible on the white plastic surfaces of both loungers	Plate 006, Plate 008, Plate 012, Plate 013, Plate 014
Courtyard side door/gate - dark wood-toned vertical planks in a galvanized metal surround, set into the boundary wall	1	GOOD	Planks and surround intact, no rot or rust noted	Plate 005, Plate 006, Plate 013, Plate 014
Dark grey wall-mounted post box/mailbox beside the courtyard gate	1	GOOD	Housing intact, no damage visible	Plate 005, Plate 006
Electric fence strand wires running along the top of the courtyard boundary wall	1	GOOD	Wires in place along the full run, no broken strands or leaning brackets visible	Plate 005, Plate 006, Plate 008, Plate 012
Black wrought-iron lantern wall lights on the courtyard-facing house wall - square frosted-glass shades divided into a 3x3 grid by black metal muntins, on curled scroll brackets, one larger and one smaller	2	FAIR	A small brown debris clump (possibly an insect nest) is adhered to the inside of one frosted glass pane, and there is general grime and weathering on the metal surround	Plate 005, Plate 008, Plate 009, Plate 015, Plate 016
White-painted expandable concertina security gate covering the sliding glass door onto the courtyard	1	FAIR	Dust and grime buildup on the white security gate bars; gate fully extended and latched at inspection	Plate 005, Plate 008, Plate 016, Plate 012
Sliding glass door from the house onto the courtyard, white aluminium surround	1	GOOD	Glazing and surround intact, no cracks noted; door standing open at inspection	Plate 005, Plate 008

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Black plastic water butt/rainwater container standing on the raised paved step beneath the downpipe	1	GOOD	Container body intact, no splits visible	Plate 008
Rainwater downpipe serving the courtyard - black plastic hopper box on the wall feeding a white PVC pipe run	1	GOOD	Hopper and pipe in place and connected	Plate 008, Plate 009
Dark ceramic/stone garden ornaments standing on the paving at the base of the courtyard wall - one vase and one lantern-shaped ornament	2	GOOD	Both ornaments intact, no chips or cracks visible	Plate 005, Plate 006, Plate 007
White PVC pool pipe (skimmer/ equipment line) lying across the corner of the pool surround	1	FAIR	Pipe lying loose across the paved surround rather than fixed or buried	Plate 007, Plate 009
Small yellow plastic pool test-kit vial floating at the pool edge	1	GOOD	Vial intact	Plate 007, Plate 010
White security/burglar bars to the courtyard-facing windows - vertical bars and a white diamond-pattern panel	1	GOOD	Bars secure in their surrounds, no rust or distortion noted	Plate 009, Plate 016, Plate 010
White-framed window with white-painted expandable concertina security gate on the courtyard elevation	1	GOOD	Window surround and gate intact; lattice fully extended	Plate 016
Small rectangular grey wall-mounted light fixture above the courtyard door	1	GOOD	Fixture in place, no damage visible	Plate 013

13 Outdoor courtyard & braai

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Built-in Jetmaster braai - black steel firebox with an oval 'Jetmaster' badge above the opening, black flip-down front cooking surface/shelf, black chimney hood/flue, cast-iron adjustable grate-height hook/lever, and a grey metal ash/wood box drawer embossed 'Jetmaster'	1	FAIR	Soot and ash residue built up inside the firebox and on the flip-down shelf, with a light dust film over the unit	Plate 017, Plate 018
Wire mesh grill basket with folding handle, sitting on the braai grate	1	POOR	Visible rust across the wire grill basket	Plate 017
Round stainless-steel undermount bar sink in the braai counter, with a single chrome wall-mounted tap and chrome U-bend plumbing beneath	1	GOOD	Bowl, tap and trap intact, no leaks or corrosion visible	Plate 019, Plate 017, Plate 018

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Grey synthetic rattan/wicker outdoor two-seater sofa with cream/off-white cushions (two back cushions and a long seat cushion split into two sections)	1	POOR	Dark smudge stain on the seat cushion fabric near its centre-right, with visible dirt marks, dark staining and creasing across the cushion covers, consistent with outdoor weathering	Plate 020
Grey synthetic rattan/wicker outdoor three-seat sofa with grey/beige cushions	1	FAIR	Cushion covers show general soiling and creasing; wicker weave shows light wear but no breaks	Plate 022, Plate 023
Grey synthetic rattan/wicker outdoor armchairs with cream/off-white seat and back cushions and large beige scatter cushions	2	FAIR	Visible dirt/grime staining on the seat cushion of the central armchair; mild creasing and wrinkling across the other cushion covers; light general wear on the wicker weave but no breaks	Plate 021, Plate 024
Grey synthetic rattan/wicker coffee table with a tempered glass top set into a rattan-wrapped surround with exposed circular wooden corner joints	1	POOR	A distinct circular amber/orange resin-like stain roughly 4-5cm across at the front-left corner of the glass top, with an adjacent whitish-green residue patch; dark stain/weathering at one wooden corner joint; light dust and smudging across the glass	Plate 021, Plate 025, Plate 022
Green woven fabric cover or cushion laid over the patio coffee table	1	GOOD	Fabric intact, no tears visible	Plate 024
Wall-mounted black flat-screen TV/monitor set into the upper alcove of the patio kitchenette unit, with a manufacturer sticker on its lower left corner	1	GOOD	Screen and housing intact, no cracks visible; unit was off throughout the record	Plate 026, Plate 024, Plate 027
Exposed copper/brass plumbing pipe with a P-trap bend and isolation valve protruding from the lower kitchenette niche	1	POOR	Pipe is exposed and unconnected, with no fixture attached; appears to be a tap or future sink connection point left incomplete	Plate 026
Cream-coloured electrical socket/switch plates on the patio and kitchenette walls	1	GOOD	Plates in place, no scorching or cracking visible	Plate 026, Plate 027, Plate 019
White concertina/trellis security gates across the doors from the patio into the house interior, with diagonal bracing and a door lock/latch mechanism	2	GOOD	Lattice, bracing and latches intact and fully extended across the openings	Plate 018, Plate 022, Plate 023, Plate 024, Plate 027
Solid dark wood door at the far right of the covered patio	1	GOOD	Leaf and surround intact, no visible damage	Plate 018
Wall-mounted lantern-style light fixture centred above the patio opening	1	GOOD	Fixture and glazing in place, no damage visible	Plate 018

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Wooden venetian blinds/shutters behind the glazed patio doors	1	GOOD	Slats intact and hanging level where visible	Plate 024, Plate 027
Potted plants in terracotta, concrete and metal planters through the rear garden and patio bed - including a large potted aloe, agave, cactus and a small cactus/succulent in a metal planter box	1	GOOD	Plants in leaf, pots intact with no chips or cracks noted	Plate 018, Plate 019
Weathered grey driftwood/root decor - a sculpture piece on the patio and a large driftwood log used as a planter display, plus a driftwood piece at the base of the patio wall	1	GOOD	Pieces sound and intact; naturally weathered grey surface	Plate 018
Garden hose, coiled and lying across the rear lawn	1	GOOD	Hose intact, no splits or kinks visible	
Small teal/turquoise planter with greenery on the patio	1	GOOD	Planter intact, plant in leaf	Plate 023

14 Garage

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Sectional garage door to the double garage, with floor track/threshold	1	GOOD	Door panels intact and operating on the track; standing open at inspection	Plate 028
Garage door operator - navy-blue plastic motor housing with red LED display mounted on a grey metal rail fixed to the ceiling, red twisted release cord running to a red plastic emergency-release pull toggle on the wall, with a wall-mounted motor control box	1	GOOD	Motor, rail, release cord and control box all in place; no damage or marks visible, surrounding walls freshly painted	Plate 029
Wall-mounted control unit branded 'DRUID', black housing with digital display and multiple labelled buttons	1	GOOD	Housing and display intact, no damage visible	Plate 030
Grey electrical distribution box mounted on the garage wall below the DRUID control unit	1	GOOD	Enclosure closed and intact, no damage visible	Plate 030
Built-in white cabinetry to the back and side walls of the garage - overhead and floor units with hinged doors	1	GOOD	Carcasses and doors intact, hinges in place, no water damage or swelling noted	Plate 028, Plate 035, Plate 032, Plate 036, Plate 037
Tall white open-shelf cubby storage units	1	GOOD	Shelving upright and intact, mostly empty	Plate 033, Plate 034

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
DEFY front-loading washing machine - dark graphite/anthracite body, round glass porthole door, digital display, single control dial, energy-rating sticker affixed to the door glass	1	GOOD	Light scuff marks on the top surface; door, dial and display all intact	Plate 038, Plate 036
DEFY tumble dryer - silver-grey body, round door, dial control, with a yellow sticky note attached to the front panel	1	GOOD	Body and door intact, no damage noted	Plate 038
Stainless-steel microwave oven standing at floor level beside the laundry appliances	1	FAIR	Door found slightly ajar; casing otherwise intact	Plate 038
Laundry sink/basin with two taps, set beside the washer and dryer	1	GOOD	Bowl and taps intact, no cracks or staining noted	Plate 032, Plate 033
Laundry basket on a small rolling stand	1	GOOD	Basket and stand intact	Plate 028, Plate 033
White fold-up ironing board	1	GOOD	Surround and cover intact	Plate 028, Plate 035
Manual push reel lawnmower, black body with red wheels	1	GOOD	Blades, handle and wheels in place, no rust noted	Plate 028, Plate 035, Plate 032, Plate 033
Electric push lawnmower, orange and black, with black grass-catcher box and a red coiled extension cord wrapped around the handle	1	GOOD	Body, catcher box and cord intact; a black plastic bucket was standing upside-down on the engine housing at inspection	Plate 031
Black plastic bucket	1	GOOD	No cracks or damage visible	Plate 031
Wooden ladder (extension type) leaning against the garage wall	1	POOR	Heavily paint-splattered and weathered, visible surface wear on the rungs and rust staining at the hinge joints	Plate 032, Plate 030
Aluminium step ladder leaning against the garage back wall	1	GOOD	Rails and steps intact, no bends or corrosion noted	
Wall-mounted fire extinguisher	1	GOOD	Cylinder and bracket in place	Plate 028
Folded wooden clothes airer/drying rack leaning against the garage wall	1	GOOD	Surround intact, no breaks visible	Plate 028
Wooden slatted bed base and headboard stored upright against the garage wall, with two grey/beige bath mats or rugs draped over the top rail	1	GOOD	Slats and surround intact where visible	Plate 031, Plate 033

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Long-handled garden and cleaning tools stored upright in the shelving - broom with red-and-silver handle, mop, red-headed garden rake, orange-tined leaf rake, spade and a black extendable pole	1	GOOD	Handles and heads intact, no breakages noted	Plate 028, Plate 035, Plate 032, Plate 033, Plate 036
Red-and-black vacuum cleaner or steam mop stored in the garage cupboard	1	GOOD	Housing intact, no damage visible	Plate 036
Cleaning supplies in a grey plastic basin on the cupboard shelf - white spray bottle, part-used yellow-labelled bottle, blue washing-up liquid bottle and other containers	1	GOOD	Containers intact	Plate 036
Capsule coffee machine, black body with white/chrome accent ring and stainless steel drip tray, stored on a cupboard shelf	1	GOOD	Body and drip tray intact, no damage visible	Plate 037
Orbital/disc sander power tool stored on the cupboard shelf	1	GOOD	Housing intact, no damage visible	Plate 037
Blue strap/tie-down stored on the cupboard shelf	1	GOOD	Webbing intact, no fraying visible	Plate 037
Small red-and-blue boxes stacked at the front of the cupboard shelf	1	GOOD	Boxes intact	Plate 037
Grey plastic wheelie/pedal bin marked 'C.C.C.' standing inside the garage	1	GOOD	Body and lid intact	Plate 032, Plate 030
Mop bucket with mop handle, and dustpan	1	GOOD	Bucket and handle intact	Plate 033, Plate 030, Plate 034
Small white waste/pedal bin standing near the garage side door	1	GOOD	Body and lid intact	
White side door with round knob, leading from the garage into the house	1	GOOD	Door leaf, surround and handle intact, no scuffing noted	Plate 033
Wall-mounted key hook	1	GOOD	Fitting secure	
White wall-mounted electrical box/socket with surface cable run	1	GOOD	Cover plate in place, cable secured	Plate 034
Small trolley/hand-truck	1	GOOD	Surround and wheels intact	
Wooden-framed panel or mirror leaning against the garage wall	1	GOOD	Surround intact where visible	
Wooden workbench top in the garage cupboard run	1	GOOD	Top intact, no splits or burns noted	Plate 036

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Aluminium folding table stored beside the laundry appliances	1	GOOD	Leg and surround intact where visible	Plate 038
Yellow-handled long tool and stacked grey/black plastic buckets	1	GOOD	Handle and buckets intact	Plate 038
Assorted stored goods on the garage shelving - shoes, storage boxes, tins and cans, a plastic bowl, a small plant pot and a brown paper bag	1	GOOD	Items stored and intact where visible	Plate 028, Plate 034, Plate 036, Plate 037
Stored cardboard boxes and flattened cardboard on the garage floor	1	FAIR	Flattened and stacked, some boxes bowed	Plate 031, Plate 032, Plate 033
Black lantern-style wall light fixture mounted on the exterior wall above the garage opening	1	GOOD	Fixture and glazing in place, no damage visible	Plate 028, Plate 035, Plate 032

15 Laundry / utility & storage

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
DEFY front-loading washing machine, dark grey/black front, round glass door, rotary programme dial (On/Off, Cotton 20/40/60+Prewash/90/Eco, Synthetics 20, Delicate/Hand Wash 40, Downwear 40, Spin+Drain, Rinse, Drum Clean) and small digital display, green 'ENERGY A+++' label on the door glass	1	POOR	Heavy dark staining/streaking down the front panel, concentrated below and around the door (possibly rust, mould or detergent residue); scuffing and grime around the door surround	Plate 039, Plate 040, Plate 041, Plate 042
DEFY tumble dryer, silver front-loader with round porthole door and timer dial, carrying a yellow 'Autodryer Operations' instruction sticker, a red/white 'DO NOT OVERLOAD THE DRUM - RECOMMENDED LOAD' warning sticker and a green energy-rating sticker	1	FAIR	General surface wear and dirt on the appliance front	Plate 039, Plate 040, Plate 041, Plate 042
DEFY microwave oven, silver/mirrored finish, standing on the timber shelf above the laundry appliances; labelled preset panel (BAKED POTATO, POPCORN, PIZZA, BEVERAGE, FROZEN DINNER, REHEAT, POWER, TIMER, CLOCK, RESET, COOK, COOK BY WEIGHT, START/STOP, DEFROST BY WEIGHT, SPEED DEFROST) and numeric keypad	1	GOOD	No dents, cracks or major wear; light smudging/fingerprints on the mirrored door surface (cosmetic)	Plate 043, Plate 039, Plate 040, Plate 041, Plate 042
Chrome double wall hook, utility recess side wall	1	GOOD	No damage observed	Plate 044
Wooden venetian blind to the utility area window	1	GOOD	No defects observed (partially visible at the edge of the view)	Plate 044

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Laundry sink/trough with two exposed chrome tap fittings above and visible P-trap plumbing beneath (recorded as a white plastic rectangular basin in one view and a stainless-steel wall-mounted trough in another)	1	FAIR	Exposed pipework beneath, no leaks or damage observed	Plate 040, Plate 042
Ironing board with green-and-cream / green-and-blue checked patterned cover	1	GOOD	Cover intact, no scorch marks observed	Plate 040, Plate 047, Plate 042
Black dustpan and brush set	1	GOOD	No damage observed	Plate 040
Yellow-handled mop with grey plastic mop bucket	2	FAIR	Bucket contains water and what appears to be cleaning solution or debris; general utility wear	Plate 040, Plate 042, Plate 041
Black plastic bucket containing small metal fittings/hardware	1	FAIR	General utility wear	Plate 040
Genesis CycloVac cyclonic vacuum cleaner (Verimark), boxed - 'The ideal compact & powerful cyclonic vacuum'	1	EXCELLENT	Stored unused in original packaging	Plate 046
Red canister-style handheld cleaning appliance (vacuum or steam cleaner), stored in the utility cupboard	1	FAIR	General storage wear; not powered up or tested	Plate 047, Plate 041
Steam iron, blue and white, with woven/braided cord	1	GOOD	No damage observed	Plate 046
Boxed DEFY-branded item (black box, appears to be a small appliance), stored on a cupboard shelf	1	GOOD	Box intact	Plate 046
White plastic multi-hook organiser	1	GOOD	No damage observed	Plate 046
Clear plastic bag containing folded white/blue fabric items with blue text (possibly aprons or linens)	1	GOOD	Bagged and stored	Plate 046
Brown plastic 'Coconut Oil' toiletry bottles (shampoo/conditioner pair)	2	GOOD	Part-used consumables	Plate 046
Cleaning consumables on the lower cupboard shelf - purple spray bottle, green/white bottle, blue-capped spray bottle, an aerosol can with red cap, a clear bottle with black cap, an orange bottle, and a pack labelled 'DRY CARPET & FABRIC CLEANER'	7	GOOD	Part-used consumables	Plate 046
Assorted stored items on the cupboard middle shelf - black shoe stretcher/boot form, round grey lid/pan, and navy and brown/tan fabric belts or straps	3	FAIR	Stored, general wear	Plate 046

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Black pod-style (Nespresso-type) coffee machine, stored on a utility cupboard shelf	1	FAIR	Stored among cleaning supplies; not tested	Plate 047
Long-handled cleaning and garden tools stored in the cupboard - black wet/dry mop system with red handle, orange plastic leaf rake, and further mop and broom handles	4	FAIR	General utility wear	Plate 047, Plate 041
Utility cupboard contents - grey plastic basin, cleaning spray bottles and bottles of liquid on the lower shelf, a brown paper bag, a coiled blue cable/strap and a black drawstring bag	1	FAIR	Cluttered/disorganised storage typical of a utility space	Plate 047
Red toolbox stored on the shelf above the laundry counter	1	FAIR	Stored, general wear; contents not visible	Plate 047
Clear plastic laundry basket	1	GOOD	No cracks or damage observed	Plate 041, Plate 042
Metal-legged side table in the laundry nook	1	GOOD	No damage observed	Plate 041
Beige stone/marble-look stool or side table	1	GOOD	No chips or damage observed	Plate 039
Glade Secrets 'Ocean Escape' air freshener can and a HellermannTyton TOP Tronic instruction leaflet stored at the distribution board	2	GOOD	Consumable and documentation, intact	

16 Kitchen

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Painted kitchen walls and splashback, grey/putty finish	1	FAIR	Faint vertical mark/shadow running down the wall from the corner near the emergency button; otherwise sound	Plate 051, Plate 066
Horizontal venetian blind to kitchen window (recorded as white slats in one view and light wood-tone slats in another), with decorative bead curtain hanging at the window edge	1	GOOD	No defects observed	Plate 051, Plate 054
Wall-mounted stainless steel utensil rail with three S-hooks	1	GOOD	No damage observed	Plate 066
SMEG freestanding range cooker, cream/off-white body, stainless steel 5-burner gas hob with black cast-iron pan supports, digital clock/timer display, front control knobs, glass-fronted main oven with long chrome handle and lower drawer/oven compartment	1	FAIR	Green/dark tarnish or residue build-up around the bases of several control knobs on the right side; dark blackened patina on the cast-iron pan supports; light dust/residue build-up around the chrome 'smeg' badge; general light wear/patina on the stainless hob surface	Plate 068, Plate 069, Plate 062, Plate 058, Plate 063, Plate 064

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
DEFY dishwasher, stainless/graphite front, built in under the worktop, recessed door handle, control panel with rotary dial selector and indicator lights, green energy-rating sticker on fascia	1	POOR	Torn/curled rubber door seal lifting away from the top of the door lining; wire rack tines bent and splayed out of alignment in places; water spot residue and small food debris specks on the interior walls	Plate 051, Plate 070, Plate 071, Plate 059
DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel bar handles, digital 'Cooling+' interior control panel, blue LED interior light strip and clear plastic door bins, set into a wall niche	1	GOOD	Interior clean with no mould, staining or residue; light fingerprint/smudge marks on the stainless steel door surfaces (cosmetic)	Plate 072, Plate 073, Plate 074, Plate 055
DEFY 4-slice stainless steel toaster, two browning dials, buttons labelled DEFROST / REHEAT / CANCEL in maroon, black cord with SA 3-round-pin plug	1	FAIR	Light dust and crumb residue and fingerprint smudges on the brushed steel body	Plate 067, Plate 051, Plate 056, Plate 061
Stainless steel undermount sink with chrome gooseneck mixer tap and associated plumbing (grey P-trap, braided flexible supply hoses, black woven cable-protector sleeve)	1	GOOD	No leaks, corrosion or damage observed	Plate 051, Plate 060, Plate 059
Pump-top liquid soap/sanitiser dispenser bottle on the counter	1	GOOD	No defects observed	Plate 051, Plate 059
Grey dish-drying rack	1	GOOD	No defects observed	Plate 059
Clear stemmed wine/cocktail glasses, stored upside down on cabinet shelf	10	GOOD	No chips confirmed; one view is indistinct, so fine chips could not be ruled out on the glassware	Plate 052, Plate 051, Plate 055
Clear glass tumblers - two tall ribbed/fluted tumblers plus a stack of approximately three shorter glasses	5	GOOD	No chips or cracks observed	Plate 052, Plate 055
Clear fluted glass vase/tumbler	1	GOOD	No defects observed	Plate 052
White and cream ceramic mugs and cups - one large white mug with handle, one small white espresso/demitasse cup, two tall handleless white cylindrical cups, one taller pale beige/putty mug with handle; three further cream ceramic mugs seen in a second cabinet view	5	GOOD	No chips observed	Plate 053, Plate 051, Plate 055
Square white ceramic saucers/side plates, stacked	5	FAIR	Light brown/orange stain or mark near the centre of the top saucer in the stack	Plate 053

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Large white dinner plates, plain, matching set	4	GOOD	Clean, no visible chips from the angle photographed	Plate 056, Plate 051
White side plates, plain, matching set	4	GOOD	Clean, no visible chips	Plate 056, Plate 054
Small white bowls, plain, matching set	4	GOOD	Clean, no visible chips	Plate 056
Medium white/cream bowls, plain, matching set	5	GOOD	Clean, no visible chips	Plate 056, Plate 054
Shallow white pasta/serving bowls	2	GOOD	No visible chips	Plate 056
Plastic cutlery organiser tray printed 'teaspoons'	1	GOOD	Drawer interior and tray clean, no cracks or damage	Plate 075
Stainless steel dinner/table spoons	5	GOOD	No damage observed	Plate 075
Stainless steel table forks	4	GOOD	No damage observed	Plate 075
Stainless steel table knives	5	GOOD	No damage observed	Plate 075
Small stainless steel teaspoons	2	GOOD	No damage observed	Plate 075
Black-handled steak/utility knife set standing in a drawer slot	5	GOOD	No damage observed	Plate 075
Black-handled kitchen knives of varying blade sizes (4) plus one black-handled meat cleaver	5	GOOD	No damage observed	Plate 075
Black plastic slotted turners/spatulas with stainless steel handles (drawer-stored)	2	GOOD	No damage observed	Plate 075
Black Y-shaped vegetable peeler	1	GOOD	No damage observed	Plate 075
Black kitchen scissors/shears	1	GOOD	No damage observed	Plate 075
Black-handled ladle/scoop with round bowl (drawer-stored)	1	GOOD	No damage observed	Plate 075
Black plastic measuring spoons on a ring	3	GOOD	No damage observed	Plate 075
Wooden cooking spoons/turners	3	FAIR	Spoon heads show dark staining and wear consistent with heavy use	Plate 075
Black-handled utensils hanging on the wall rail/hooks (observed as a slotted serving spoon, a solid serving spoon and a stainless wire whisk in one view; a ladle and two turners in another)	3	GOOD	No damage observed	Plate 066, Plate 054

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Stainless steel pots/saucepans of varying sizes with glass lids and black/grey silicone-covered handles, in a grey non-slip lined drawer	4	GOOD	Used but sound, no dents or rust; light water spot/residue marks on the glass lid of the front pot	Plate 076
Black enamel oven grill/roasting tray, ridged and flat sections	1	FAIR	Staining/residue marks across the ridged section of the tray	Plate 057
Oven mitt with floral/patterned fabric (blue, yellow, orange) and quilted pot-holder/oven glove in pink and green patterned fabric	2	GOOD	No damage observed	Plate 057
Folded appliance instruction/warranty document printed 'SAFEWAY STOVETOP KETTLE', stored in a kitchen drawer	1	GOOD	Document intact	Plate 057
Under-sink cleaning consumables - Sunlight Platinum dishwashing liquid ('5X GREASE CUTTING POWER'), a green packet of Heavy Duty scourers, a bundle of steel wool scourers in plastic packaging, and a dish brush with red plastic head	4	GOOD	Part-used consumables	Plate 060
Cleaning items in the cabinet beside the dishwasher - green sponge/scourer, green cloth and an amber-coloured dishwashing liquid bottle with red cap	3	GOOD	Part-used consumables	
Backless bar stools, galvanised/raw steel finish with cross-braced legs and square wooden seat tops, at the breakfast bar	2	GOOD	No visible defects on the stools	Plate 065
White cylindrical ceramic canister with wooden lid, on the island counter	1	GOOD	No defects observed	Plate 058, Plate 064, Plate 065
Folded blue-and-white striped cloth/napkin on the island counter	1	GOOD	No staining observed	Plate 064
Refrigerator accessories - ice-cube tray, two blue plastic ice/freezer blocks and white egg-crate style trays	4	GOOD	Clean, no damage observed	Plate 073

17 Lounge

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Built-in fireplace recess with black metal gas/radiant fire insert, visible ribbed radiant bars and tiled hearth floor, set into a white-trimmed plaster surround	1	FAIR	Sooty/blackened staining inside the fireplace insert (expected wear from use); small chip/notch in the plaster step beside the fireplace opening; recess interior dark and sooted, limiting close assessment in the s	Plate 077, Plate 078, Plate 079, Plate 080
Fireplace tools - small black hearth brush and a black poker/tool, resting on the tiled hearth and hanging inside the fireplace opening	2	GOOD	No damage observed; both items in use inside the fireplace recess	Plate 077, Plate 078
Grey woven-fabric wingback armchair, buttoned/tufted back panel with 12 buttons in a 3x4 grid, pale wood tapered legs	1	FAIR	Visible vertical crease/wear marks and light staining on the lower front seat cushion; fine surface fuzz/pilling texture across the fabric	Plate 077, Plate 078, Plate 081, Plate 082, Plate 083, Plate 084, Plate 085, Plate 086, Plate 079, Plate 080
Grey/charcoal fabric L-shaped sectional sofa with chaise section	1	FAIR	Dark stain/blotch marks on the seat cushion of the chaise section; a further light discoloured water-mark-like patch on the chaise cushion; fine dust/lint visible on the armrest fabric	Plate 087, Plate 084, Plate 088
Scatter cushions for the grey sectional sofa, matching grey / charcoal-navy velvet-look fabric	5	GOOD	No defects observed. Count varies between photographs: three counted on the backrest, five counted piled at the armrest; five is the highest verified count and is recorded here	Plate 087, Plate 084, Plate 088
Tan/caramel-brown leather sofa, corner configuration with two sections meeting at a corner, two back and two seat cushions, wooden block legs, top-stitched seams	1	FAIR	Heavy creasing and wrinkling across all leather cushions with a mottled, variegated worn-in patina over the whole visible surface; the observer could not distinguish an intentional distressed-leather finish from genuine wear; no tears or stains visible	Plate 089, Plate 081, Plate 090, Plate 091
Round live-edge wood-slab coffee table (tree-trunk cross-section, visible growth rings and retained bark edge) on thin black metal hairpin legs	1	FAIR	Natural crack/split running across the wood-slab table top	Plate 087, Plate 082, Plate 083, Plate 084, Plate 088
Wooden TV console / low media bench with visible knots in the timber top	1	FAIR	Small dark marks/scuffs on the wooden console top surface	Plate 087, Plate 082, Plate 083, Plate 084, Plate 085, Plate 086

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
SAMSUNG flat-screen television, black, standing on black plastic feet on the TV console; 'SAMSUNG' legible on the lower bezel	1	GOOD	No defects observed; screen off in every photograph, so display function not verified	Plate 082, Plate 083, Plate 092, Plate 084, Plate 085, Plate 086
SAMSUNG television remote control, black with a red power button, resting on the TV console	1	GOOD	No damage observed	Plate 082, Plate 086
SAMSUNG wireless satellite speakers, black with chrome/cream bases, wall-mounted high in the room corners ('SAMSUNG' printed on the face of each)	2	GOOD	No damage observed to the units themselves; both mounted high on opposite walls near the ceiling	Plate 093, Plate 092, Plate 094
Soundbar-style audio unit sitting beneath the television screen on the TV console	1	FAIR	Observed at distance only; brand and model text not legible and surface condition not resolvable at that resolution	Plate 084
DSC wall-mounted alarm keypad, white, zone numbers 1-16 printed on the fascia	1	FAIR	Yellow warning-triangle indicator illuminated on the panel, suggesting a fault or unset zone; zones 1 and 2 lit red; small dark specks/marks on the wall below the panel	Plate 095
Chevron-pattern fabric floor poufs / storage cubes - two red-and-cream, one black-and-cream - stored beneath the TV console	3	GOOD	No defects observed	Plate 096, Plate 082, Plate 083, Plate 084, Plate 085, Plate 088
Organic star/leaf-shaped carved wood side table with a hollowed bowl-like natural-edge top, on three thin black angled metal legs	1	GOOD	No defects observed on this piece	Plate 081
Rustic reclaimed-wood slatted chest/trunk in use as a coffee table, rough-cut slats of varying tone with visible gaps	1	FAIR	Visible splits/cracks in the wood slats of the trunk top; one slat raised or misaligned relative to the others	Plate 081
Cowhide-pattern rug, white and brown patches	1	GOOD	No defects observed	Plate 079
Small round grey rug beneath the tufted armchair	1	GOOD	No defects observed	Plate 085

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Blue/navy upholstered armchair with wooden arm surround and a matching blue scatter cushion (described in one photograph as the corner of another blue upholstered seat; configuration not fully resolved)	1	GOOD	No defects observed; one of the three views is indistinct, limiting fine surface assessment	Plate 082, Plate 083
Wishbone-style wooden chair with woven paper-cord seat, standing in the lounge beside the fireplace (matches the dining chairs; may be one of the dining set relocated - not confirmed)	1	GOOD	No defects observed	Plate 078
Wood-slat / faux-wood venetian blinds to the lounge windows and the sliding balcony door (recorded as one set; the number of individual blinds is not determinable from the photographs)	1	GOOD	No broken, bent or missing slats observed; blinds shown variously part-open and part-closed	Plate 089, Plate 081, Plate 082, Plate 097, Plate 084, Plate 085, Plate 086, Plate 079, Plate 080, Plate 091
Sliding glass door to the balcony with white metal security grille/gate	1	GOOD	No damage observed to the glazing or the security grille. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 081
Lounge flooring - wood-look plank tile in a mixed herringbone/staggered pattern in the main area, transitioning to lighter solid timber strips and to wide-plank grey-brown reclaimed-look boards at the fireplace end	1	FAIR	A distinctly darker, almost black-brown discoloured patch/streak running the length of one plank near the centre of the room; a wide lighter discoloured patch on the floor by the armchair consistent with sun-fading or a rug recently removed; no cracks or chips observed elsewhere. Fixed finish: recorded for condition, not as replaceable contents	Plate 077, Plate 078, Plate 096, Plate 084, Plate 088, Plate 079, Plate 080
Lounge wall finishes and paint - recorded variously as pale cream/off-white, pale grey, greige, sage-green and grey-blue across the different wall planes	1	FAIR	Small dark smudge/mark on the wall near the ceiling corner; a small dark mark/spot on the wall beside and below the television, possibly a nail hole or scuff; several small dark specks on the wall beside the corner speaker; scattered small dark specks/marks on the wall below the alarm keypad. Fixed finish: recorded for condition, not as replaceable contents	Plate 089, Plate 093, Plate 095, Plate 094, Plate 086
Ceiling - white panelled/coffered ceiling with raised trim lines forming a geometric pattern	1	FAIR	A few small dark specks/marks on the ceiling near the panel seams. Fixed finish: recorded for condition, not as replaceable contents	Plate 092

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Decorative white cornice/ coving to the wall-ceiling junction	1	FAIR	Visible crack/gap in the plaster or trim where the door architrave meets the ceiling corner, directly beside the wall-mounted Samsung speaker. Fixed finish: recorded for condition, not as replaceable contents	Plate 093, Plate 092, Plate 094
White painted skirting boards throughout the lounge	1	FAIR	A scuff or chip mark on the white skirting board directly in front of the fireplace opening; skirting elsewhere shows no damage in the views available. Fixed finish: recorded for condition, not as replaceable contents	Plate 077, Plate 087, Plate 083, Plate 088, Plate 080
Recessed ceiling downlights (small round fittings; one observed illuminated warm white)	2	GOOD	One fitting observed lit; no damage to the fittings observed. Count taken from the widest ceiling views available	Plate 092
Ceiling-mounted smoke detector near the lounge corner	1	FAIR	Observed only in a significantly indistinct surround; make, model and indicator state not legible and function not verified	
Wall-mounted white intercom / entry-phone handset with coiled cord, with an adjacent white single switch and a small round wall-mounted device (doorbell chime or sensor; not identified)	1	GOOD	No damage observed; coiled cord hanging loose on the wall	Plate 089, Plate 091
Small chrome/silver wall hooks fixed to the lounge wall, both empty	2	GOOD	Securely fixed, no damage observed	Plate 093
Two-gang toggle light switch on the lounge wall beside the doorway	1	GOOD	Plate intact, no cracks or scorching observed. Fixed fitting: recorded for condition, not as replaceable contents	Plate 085
Set of keys hanging on a hook / at the switch plate beside the lounge doorway	1	GOOD	Recorded as observed; the keys themselves are not identified and no value is assigned	Plate 085
Internal door to the lounge - white painted door with silver lever handle and deadbolt/ keyhole plate, in a white- painted surround	1	GOOD	No visible damage to the door, surround or ironmongery in this view. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 085

18 Dining

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Wooden dining table with tapered legs (recorded as square and dark-stained in one photograph and as rectangular and medium-brown in another; shape and finish not fully resolved between the two views)	1	FAIR	Faint watermark/blotch discoloration in the timber of the table top	Plate 098, Plate 099
Wishbone-style wooden dining chairs with woven paper-cord (rush) seats, matching the dining table	4	GOOD	No fraying, breaks or staining observed in the seat weave or surrounds	Plate 098, Plate 099
Dining area flooring - solid honey-brown pine plank boards with visible knots and grain	1	FAIR	A round hole/knot-like opening in one floorboard; a visible seam/gap line running across the boards; a rectangular seam/outline in the floor with a small round metal fitting embedded within it, consistent with an underfloor access hatch or a repair (not confirmed). Fixed finish: recorded for condition, not as replaceable contents	Plate 098, Plate 099
Dining area wall finish (pale grey paint) with a white double round-pin wall socket	1	GOOD	No cracks, marks or damage observed to the wall or the socket plate. Fixed finish: recorded for condition, not as replaceable contents	Plate 099
Black cylindrical flue pipe (possibly a wood-burning stove flue) rising at the edge of the dining area	1	FAIR	Only partially visible at the edge of a single view; type, fixing and condition not confirmed. Recorded for condition, not as replaceable contents	Plate 099
Passage/hallway flooring - wood-look plank tile running from the lounge doorway toward the front door	1	GOOD	No visible cracks, stains or chips; light glare across the mid-floor is consistent with a glossy tile finish rather than damage. Fixed finish: recorded for condition, not as replaceable contents	Plate 100
Passage/hallway wall finish - grey/light-taupe to cream-beige paint with white skirting	1	GOOD	No cracks, scuffs or marks observed in the views available. Fixed finish: recorded for condition, not as replaceable contents	Plate 100, Plate 101
Front entrance door - white, with narrow glass side panels	1	GOOD	No damage observed; photographed at distance down the passage, so ironmongery and seals were not inspected close up. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 100
Internal hinged doors off the passage - white painted, in white surrounds (one on the left of the passage, one standing ajar to the bathroom beyond)	2	GOOD	No visible damage to leaves, surrounds or hinges. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 100, Plate 101

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Two-gang white light switch on the passage wall	1	GOOD	Plate intact, no cracks or marks observed. Fixed fitting; recorded for condition, not as replaceable contents	Plate 101
White console table / shoe rack standing against the passage wall by the front door	1	GOOD	No damage observed; photographed at distance, so surface detail is not resolvable	Plate 100
White decorative wire/lattice screen or gate, seen from the passage in the room to the right of the front door (position beyond the passage; area assignment provisional)	1	GOOD	No damage observed; viewed only at distance from the passage	Plate 100

19 Main bedroom suite

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Double/queen bed — white upholstered divan base with a bare mattress; the mattress ticking is a quilted cream/pink-and-white fabric printed with the repeating brand text "Rest Assured" in red lettering with a blue logo mark. No headboard, no bedding, linen or pillows fitted	1	FAIR	Mattress is entirely bare with no bedding or linen fitted (property is part-furnished); no tears, sagging or staining visible on the ticking	Plate 102, Plate 103, Plate 104, Plate 105
Pine bedside tables flanking the bed — a taller narrow one at the head end and a lower, wider one with an open lower shelf at the foot side (mismatched pair)	2	GOOD	Natural wood grain and knots visible, varnish sound, no chips or water rings observed	Plate 102, Plate 106, Plate 103
Large white built-in wardrobe spanning the wall — three double-door hanging sections with rails and shelving above a built-in bank of drawers; visible metal cabinet hinges (three per door) and drawer interiors lined in dark grey/charcoal	1	GOOD	No damage to doors, rails, shelves or drawer boxes; all hanging sections and drawers are EMPTY apart from a single wire clothes hanger left on the rail in the left-hand section	Plate 107, Plate 108, Plate 109
White multi-drawer chest / drawer unit standing in the room (seen directly in one view and in mirror reflection in another; may form part of the fitted wardrobe run — to confirm)	1	GOOD	No damage observed; partial view only	Plate 107, Plate 105
Wooden desk or side table with visible legs standing at the window end of the room	1	GOOD	No damage observed; partial view at the edge of the view	Plate 105
Sliding glass door / window unit opening to the garden, glazed and framed	1	GOOD	Glass unbroken, surround straight; greenery visible beyond	Plate 102

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Wooden-slat / faux-wood venetian blinds to the sliding door and the bedroom windows	2	FAIR	One section of slats hangs unevenly/crookedly and is raised higher than the rest, leaving a gap; the lower section of the second window's blind also hangs tilted/uneven. Remaining slats straight and undamaged	Plate 102, Plate 107, Plate 105, Plate 109, Plate 110
White diamond/square-grid burglar-bar security grilles fitted externally to the glazing	2	GOOD	Grid straight and intact, no rust or distortion visible. Note: numerous water spots/droplets visible on the window glass behind the blinds	Plate 102, Plate 107, Plate 110
Recessed ceiling downlights set into the sloped ceiling (two illuminated in one view with a third dimmer fitting further along)	3	GOOD	Fittings seated flush, no scorching or discolouration observed	Plate 102, Plate 107, Plate 108
Retractable pleated/concertina wooden-slat skylight blind system in light natural timber, with two horizontal tensioning wires threaded through metal clips along the slats, mounted beneath a glass skylight panel	1	GOOD	Slats intact and evenly pleated, tensioning wires and clips in place; glass skylight above sound	Plate 111
Wall-mounted white sensor/detector (alarm PIR or smoke detector) fixed high on the wall at the ceiling junction	1	GOOD	Casing clean and securely mounted	Plate 102
White wall-mounted power sockets, including a double socket beside the bed	2	GOOD	Face plates intact, no scorching or cracking observed	Plate 102, Plate 106, Plate 103
White panelled bedroom door with round silver doorknob and visible keyhole lock	1	GOOD	Paint finish sound, no chipping or scuffing observed	Plate 104
Angled/cathedral white ceiling with white cornice and a grey painted wall band below the cornice — recorded for condition only	1	GOOD	Visible seam/joint lines run diagonally across the ceiling (panel or bulkhead lines); no cracking, staining or damp observed	Plate 102, Plate 108
Grey / pale grey-green painted wall finish with white skirting boards — recorded for condition only	1	GOOD	No visible defects on the wall surfaces in any view; paint even and skirting sound	Plate 107, Plate 106
Honey-toned pine plank timber flooring with visible knots and a polished/glossy finish — recorded for condition only	1	GOOD	Boards sound with a glossy sheen, no cracks, stains or water damage visible	Plate 104, Plate 109, Plate 103

20 Main en-suite bathroom

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Paired white ceramic vessel/bowl basins set on the timber vanity countertop — left basin a rounded conical bowl, right basin a more oval/asymmetric bowl; both with visible overflow holes and chrome pop-up waste fittings	2	GOOD	No chips or cracks visible on either bowl	Plate 112, Plate 113, Plate 114, Plate 115, Plate 116
Chrome gooseneck-style single-lever mixer taps serving the paired basins (left tap tall gooseneck, right tap shorter)	2	GOOD	No corrosion or drip staining observed on the tapware itself	Plate 112, Plate 114, Plate 115, Plate 116
Double vanity unit — white floating cabinet carcass with a reddish-brown/ bamboo-look varnished timber countertop, drawers below, partly supported on a single thin metal leg; drawer interior has a cut-out access panel for the plumbing riser	1	GOOD	Drawer left pulled fully open and empty except for a loose grey rubber/ plastic fitting (spare basin waste or grommet) lying in the drawer base; no damage to the carcass observed	Plate 114, Plate 116
Rectangular/square white-framed wall mirrors, one above each basin	2	GOOD	No cracks, chips or de-silvering observed	Plate 112, Plate 113, Plate 115, Plate 117
Chrome wall-mounted cup / toothbrush holder fixed to the wall between the two mirrors	1	GOOD	Good	Plate 113, Plate 117
Chrome cylindrical wall-mounted dispenser (soap or lotion) fixed beneath the mirror to the right of the basin	1	GOOD	Good	Plate 115
Large walk-in shower enclosure with frameless glass screen/door separating the shower from the rest of the room	1	GOOD	Glass clean and unbroken, no chipping observed to the screen edges	Plate 112, Plate 113, Plate 118, Plate 119
Chrome shower fittings — rectangular/ rose shower head on a rigid angled wall arm, plus a separate chrome round mixer valve with visible tubing running down the tiled wall	1	GOOD	No visible limescale build-up or corrosion observed	Plate 112, Plate 118, Plate 119
Shower floor and feature wall in beige/ brown checkerboard mosaic tiling with a chrome square floor drain grate — recorded for condition only	1	GOOD	Grout lines appear intact, no cracks, staining or mould visible in any view	Plate 112, Plate 118

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Large-format beige/taupe rectified wall tiling to the shower and vanity walls — recorded for condition only	1	FAIR	Pale mineral/water staining visible on the tiled wall behind the basins; grout lines elsewhere appear intact with no cracks or mould	Plate 114, Plate 118
White two-piece close-coupled toilet with cistern and seat	1	GOOD	No cracks or chips observed to pan, cistern or seat	Plate 112, Plate 115, Plate 116
Wall-mounted toilet-roll holder with one roll loaded; spare toilet rolls stacked on the cistern lid (one spare roll plus another item in one view, two spare rolls in another, three spare rolls in another)	1	GOOD	Holder secure; loose stock counts differ between views and are recorded as observed	Plate 112, Plate 115, Plate 116
Beige / tan-striped bath towels hung over the rail beside the window and over the heater rail	2	GOOD	No tearing, staining or fraying visible	Plate 112, Plate 116
Wall-mounted panel heater with a small adjacent thermostat / control panel, and the towel rail/radiator carrying a beige towel	1	GOOD	Casing intact, no scorching or discolouration observed	Plate 112
Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook, each with hinged double doors, internal hanging rails and shelving	2	GOOD	No surface defects on the joinery; both units left with doors standing open and interiors entirely EMPTY (bare hanging rails and shelves, no contents)	Plate 113, Plate 120, Plate 121, Plate 122
Built-in white dressing table set in a recessed nook between the wardrobes — knee-hole desk surface, square wall mirror above, and a bank of drawers below (five drawer fronts visible)	1	GOOD	Drawers left half-open and empty; no chips or delamination observed to the fronts	Plate 113, Plate 120, Plate 121, Plate 122
Full-length mirrored sliding wardrobe door with silver/aluminium surround	1	GOOD	Mirror face unbroken, surround straight	Plate 122
Tall white built-in cabinet with hinged door, plus an adjacent built-in white bench/shelf unit with drawers beneath	1	GOOD	Cabinet door observed standing ajar; no damage visible	Plate 117
Window set into the shower wall above head height, fitted with an aluminium venetian blind; a second window with pale blue/white horizontal venetian blinds to the side of the shower	2	GOOD	Slats straight, no bent or missing slats observed	Plate 112, Plate 119
Wide-board pine plank timber flooring throughout the en-suite (unusual for a bathroom) with a tiled threshold into the shower — recorded for condition only	1	FAIR	Visible seam/joint gap in the wooden flooring near the shower threshold; floor transition from wood to tile at the shower threshold otherwise appears intact; boards show natural knots, no water damage or cupping observed	Plate 113, Plate 120, Plate 114, Plate 116

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Grey/taupe painted walls with white coved cornice, white ceiling and white skirting – recorded for condition only	1	GOOD	Paint even, no cracking, damp staining or scuffing observed	Plate 113, Plate 121
Recessed ceiling downlights	1	GOOD	Fittings seated flush, no scorching observed; exact count not determinable from the record (at least one spotlight visible per view)	Plate 112, Plate 120, Plate 121
White shelving unit standing at the far right of the room	1	GOOD	No damage observed; visible only at the edge of the view	Plate 112
White electrical light-switch plate on the wall beside the mirror	1	GOOD	Plate intact and unmarked	Plate 117

21 Bedroom 2

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Double bed with a natural wood slatted headboard, carrying a bare mattress whose ticking fabric is printed repeatedly with the brand text "REST ASSURED"	1	FAIR	Mattress fully bare with no bedding or linen fitted, exposing the printed ticking; no tears or staining visible	Plate 123, Plate 124, Plate 125
Second bare mattress bearing the "Rest Assured" brand print in red script with a blue logo mark, resting at floor level – observed in one view lying directly on the floor with no visible bed base, and in another on a low base	1	POOR	Poor for use – mattress resting directly on the floor with no visible bed base and no bedding; ticking itself shows no tears or staining	Plate 126, Plate 127
Cream divan-style bed base with a woven honeycomb/diamond-pattern fabric cover, resting flush on the floor with no visible legs	1	FAIR	No legs or surround visible, sits directly on the timber floor; fabric cover clean with no tears or marks observed	Plate 128
Small pine bedside tables/stools with an open lower shelf, in unfinished/natural varnished pine – a matching pair, one at the bed head and one across the room	2	FAIR	Visible wood knots and small round blemish/knot marks across the table top, a dark stain/knot mark near the front-left corner, and minor varnish wear with sheen variation on the top surface	Plate 124, Plate 126, Plate 127, Plate 129, Plate 130
Built-in white melamine wardrobe run with multiple hinged doors and dark round handles/knobs – one section with a single hanging rail and shelf above, one section of five open adjustable shelves, a narrow vertical column of open cubbies, a further hanging rail section, and a shoe/shelf cubby at the base; dark bronze/black metal cabinet hinges	1	GOOD	Shelves, rails and hinges clean and undamaged, hinges show normal functional wear; the entire interior is EMPTY and unused, with doors left standing open	Plate 123, Plate 131, Plate 129, Plate 130

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Empty white plastic clothes hangers left on the wardrobe hanging rail	4	GOOD	Three to four hangers observed, undamaged	Plate 131
Cream/off-white wooden venetian blind to the bedroom window, with two beige/gold braided pull cords ending in wooden acorn-shaped pulls and a separate tilt-cord ladder	1	GOOD	Slats straight and undamaged; slight dust visible on some slats	Plate 125, Plate 123, Plate 131
Recessed ceiling downlights set into the sloped/angled ceiling	2	GOOD	Fittings seated flush, no scorching observed	Plate 123, Plate 131
White double electrical wall sockets (South African 3-pin type) mounted low on the wall near the bed head and beside the bedside table	2	GOOD	Face plates intact, no scorching, cracking or discolouration	Plate 124, Plate 126, Plate 127
White panelled bedroom door to the hallway	1	GOOD	Paint finish sound, no chipping or scuffing observed	Plate 132
Sloped/angled white ceiling — recorded for condition only	1	GOOD	No cracking, seam separation, staining or damp observed	Plate 123
Sage-grey / sage-green painted wall finish with white skirting boards — recorded for condition only	1	FAIR	A faint horizontal smudge mark at roughly shoulder height on one wall, and a faint diffuse smudge/mark at mid-height on another wall with no clear cause; paint otherwise even and skirting sound	Plate 126, Plate 127
Honey-toned pine plank timber flooring with numerous visible knots — recorded for condition only	1	GOOD	Numerous natural knots across the boards (inherent to the pine, not damage) and board seam gaps where planks meet (normal for this floor type); no cracks, stains or water damage visible	Plate 132

22 Second bathroom

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
White oval built-in bathtub set into a cream/beige large-format tiled surround with tiled deck and front skirt panel	1	GOOD	Tub surface glossy and clean, no cracks or chips visible on the tub or the tiled surround; grout lines intact	Plate 133, Plate 134, Plate 135, Plate 136
Wall-mounted chrome bath mixer tap with a separate hand-held shower attachment on a bracket, plus chrome overflow drain	1	GOOD	No corrosion or limescale build-up observed	Plate 133, Plate 134
Chrome circular flush-mounted jet/inlet fitting on the inner wall of the bathtub near the overflow drain (spa/jacuzzi-style bath)	1	GOOD	Fitting seated flush, no staining around the collar	Plate 134

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Small square access/inspection panel cut into the tiled skirt at the base of the bath (plumbing access)	1	FAIR	Noted because the square cut-out in the tiled skirt reads as a defect if not an intentional access hatch; edges otherwise clean	Plate 133, Plate 136
White round countertop-mounted (vessel) basin with chrome single-lever mixer tap and chrome pop-up waste	1	FAIR	Small dark mark/residue spot near the drain area inside the basin; no chips or cracks otherwise	Plate 133, Plate 137, Plate 138
Vanity unit beneath the basin – white cabinet surround with a wood-toned, ridged teak-look slatted countertop and a drawer	1	GOOD	Drawer pulled fully open and completely empty with a grey-lined interior; no damage inside or to the carcass	Plate 137, Plate 138
Mirror mounted on the wall above the basin	1	GOOD	No cracking or de-silvering observed (partial view only)	Plate 133
White close-coupled toilet with cistern, seat and lid, chrome dual-flush button on the cistern lid	1	GOOD	Clean, no visible cracks, chips or staining to pan, cistern or seat	Plate 134, Plate 135, Plate 139
Chrome wall-mounted toilet-roll holder carrying a single partially-used white paper roll	1	GOOD	Holder secure and unmarked	Plate 139
Built-in white melamine linen cupboard with six vertical compartments and hinged doors	1	GOOD	Shelving clean and undamaged, hinges show no wear issues; five of the six compartments are EMPTY	Plate 140, Plate 141
Towel stock held in one compartment of the linen cupboard – two rolled cream/beige towels with a subtle patterned stripe seen in one view; a stack of approximately four to five rolled tan/beige towels with one patterned beige towel folded on top seen in the other	1	GOOD	No staining, fraying or tearing observed; counts differ between the two views and are recorded exactly as seen	Plate 140, Plate 141
Bath towels in use – a white/cream striped bath towel hung over the tiled bath ledge, and a white towel hanging at the side of the bath	2	GOOD	No staining or fraying observed	Plate 134, Plate 136
Windows fitted with white venetian blinds – one above the bath and one beside the basin	2	GOOD	Slats appear straight, none bent or missing	Plate 140, Plate 133
Wood-look plank tile flooring in grey-brown/dark brown tones (distinct from the honey-pine timber floors elsewhere in the property) – recorded for condition only	1	FAIR	Floor trim/transition strip forms an odd raised outline near the corner, which could indicate a floor-level change or a repair; tiles otherwise sound with no cracking	Plate 133, Plate 134, Plate 139
Cream/beige wall tiling to the bath surround and behind the basin, with matching tiled skirting – recorded for condition only	1	GOOD	Grout intact, no visible staining, mould, cracking or chipped tiles	Plate 137, Plate 134

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Painted wall finish — two-tone, light grey/blue on one wall and beige/tan on the return corner, with white skirting boards — recorded for condition only	1	GOOD	Paint even, no scuffing, marking or damp staining observed	Plate 139, Plate 138

23 Guest powder room

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Round white ceramic vessel/bowl-style basin mounted on a wood-toned vanity top, with chrome mixer tap and chrome pop-up drain	1	GOOD	No chips, cracks or staining observed to the bowl or tap	Plate 142
White-framed mirror / frosted-opaque glass panel mounted on the wall above and beside the basin	1	GOOD	Glass intact, surround unmarked	Plate 142
White panelled entrance door with horizontal grooves, chrome round door handle and visible lock mechanism	1	GOOD	Paint finish sound, no chipping or scuffing observed	Plate 142
Warm taupe/greige painted wall finish — recorded for condition only	1	GOOD	No visible defects in the wall paint from the angle available	Plate 142

24 Additional bedroom — attribution not resolved

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
UNATTRIBUTED ROOM A (single-bed room, pale grey/blue walls, casement window) — single bed with a bare mattress covered only by a quilted white mattress protector, no fitted sheet or bedding	1	FAIR	Mattress is bare apart from a quilted white protector, with no sheet or bedding fitted; no tears or staining visible	Plate 143
UNATTRIBUTED ROOM A — small square two-tier pine side table (top surface plus lower shelf), varnished, with visible knots and natural grain	1	GOOD	Varnish sound, visible wood knots inherent to the timber, no chips or water rings observed	Plate 143
UNATTRIBUTED ROOM A — small wooden stool/table with turned legs, standing near the window	1	GOOD	No damage observed; seen at distance in the background	Plate 143
UNATTRIBUTED ROOM A — sash/casement window fitted with white venetian blinds, and a white double electrical wall socket with South African plug points	1	GOOD	Blind slats straight and partially open, socket face plate intact and unmarked	Plate 143

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
UNATTRIBUTED ROOM A – pale grey/blue painted walls, white skirting boards and warm honey-toned pine strip flooring – recorded for condition only	1	GOOD	Walls appear smooth and unmarked, flooring in good condition with no cracks, gaps or staining observed	Plate 143
UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor) – wooden storage trunk/crate approximately knee height (~60cm), built from mixed-tone patchwork wood block tiles/veneer, closed, standing in the corner near the window	1	GOOD	No splitting, damage or missing blocks observed to the veneer surface	Plate 144, Plate 145, Plate 146, Plate 147
UNATTRIBUTED ROOM B – black cable/adaptor running from the wooden crate to a wall socket, and a small black object (possibly a small bin or speaker) standing beside the crate	1	FAIR	Loose trailing cable running across the floor from the crate to the socket; object beside the crate not identifiable with certainty	Plate 144, Plate 145
UNATTRIBUTED ROOM B – window with a wooden surround and white venetian blinds, looking out onto a plain grey wall beyond	1	FAIR	Blinds partially open, slats appear sound; strong light obscures a full view of the blind condition	Plate 144, Plate 147
UNATTRIBUTED ROOM B – recessed ceiling downlights (two) and a small white wall-mounted fixture near the ceiling corner (sensor/detector, vent, speaker or alarm keypad – not identifiable)	1	GOOD	Fittings seated flush and securely mounted; the wall fixture cannot be identified with certainty from the record	Plate 144, Plate 146
UNATTRIBUTED ROOM B – white electrical wall sockets/switch plates on the left and right walls at skirting height	3	GOOD	Plates intact, no scorching or cracking observed	Plate 146, Plate 147
UNATTRIBUTED ROOM B – white ceiling with a stepped bulkhead detail – recorded for condition only	1	FAIR	Hairline seam/crack lines visible in the ceiling bulkhead following the angled step pattern	Plate 144
UNATTRIBUTED ROOM B – sage-green/grey painted walls with white skirting boards – recorded for condition only	1	FAIR	Light reflective glare patches on the left wall (either paint sheen variation or camera flash reflection, not resolvable); skirting sound and unmarked	Plate 146, Plate 147
UNATTRIBUTED ROOM B – wood-look plank tile/laminate flooring in brown tones – recorded for condition only	1	FAIR	Visible colour/tone variation between individual planks giving a patchwork appearance; glossy glare/sheen inconsistency across several planks; grout-like seams between planks with slight colour mismatch on some boards; darker rectangular patches and scattered lighter scuff marks on the floor (wear, staining or shadow – not resolvable from the record)	Plate 145

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
UNATTRIBUTED ROOM C (taupe/grey walls with cornice, indistinctly recorded) — window fitted with white-slat venetian blinds, a wall-mounted security/PIR sensor showing a live red LED, a white double wall socket, and three recessed ceiling downlights; the edge of a wooden furniture item is visible at the the bottom of the view	1	FAIR	Sensor LED illuminated, indicating the unit is powered; a diagonal seam/line runs across the ceiling, possibly a board joint. Detail at this position is not established	Plate 148

25 Additional bathroom — attribution not resolved

ITEM	QTY	CONDITION	AS OBSERVED	PLATES
Glossy beige/cream large-format tiled wall with a reflective glass screen (likely a shower screen) and an adjacent window with horizontal blinds — recorded for condition only. Detail at this position is not established, so it cannot be tied to a specific bathroom	1	NOT	Not assessable — no defects can be confirmed; the detail here is not established	

26 Services, metering and keys at handover

ITEM	RECORDED	NOTE
Electricity meter	To be read at handover	Prepaid (Econ unit); DB board & meter photographed.
Water meter	To be read at handover	Municipal; locate at boundary.
Gas	To be read at handover	Smeg hob is gas — confirm bottle location & level.
Geyser / hot water	To be read at handover	Electric geyser in garage/laundry roof space.
Rainwater tank	~200L — present, good	Roof-gutter fed; feeds pool/irrigation.
Front / pedestrian gate	Keys: __ Remote: __	Motorised wood-clad sliding gate.
Garage door	Remote: __	Motorised motor — photographed.
Security trellis / burglar gates	Keys: __	Rear trellis gate; burglar bars throughout.
Alarm / electric fence	Code held by: __	Electric perimeter fence + DSC alarm panel.
House / door keys	Sets handed over: __	Confirm count with tenant at handover.

Important. This is a photographic condition record made on a single date. It is not a structural, electrical, gas, damp or compliance survey; nothing was opened up, moved or tested, and no comment is offered on anything concealed. Severity is an assessment of the consequence of the observation, not of the cost of putting it right. Where an observation is described as cosmetic or as fair wear, that is an opinion offered to assist the parties and is not a determination of liability between landlord and tenant. AssetProof is not an insurer, loss adjuster, assessor, broker or certified valuer.