

Photographic Condition Inspection

Room-by-room, surface-by-surface schedule of condition — long-term letting (ingoing standard)

Property	Sample condition inspection · Vredehoek, Cape Town
Reference	C0020U
Type	House — 2 bedroom / 2 bathroom, partially furnished
Inspection date	2026-07-20
Inspected by	AssetProof
Evidence base	107 photographs + 2 walkthrough videos (targeted stills extracted)
Prepared by	AssetProof · AssetProofSolutions.com
Status	Sample — de-identified for public sharing

Sample report. A genuine AssetProof photographic condition inspection, de-identified for public sharing — the property's identity, address and all street / exterior views have been removed. Real client reports are confidential and more detailed still. See more at AssetProofSolutions.com.

Purpose & method

This report is the photographic record of the condition and cleanliness of every accessible surface — ceilings, walls, floors, skirtings, doors, windows, built-in cupboards, light fittings and fixtures — in each room, on the inspection date above. It is the evidence baseline against which the property is compared at outgoing, and the reference for any deposit assessment. All photographs were taken on the inspection date. Where a surface was not captured in a dedicated still photograph, a targeted frame has been extracted from the walkthrough video and is labelled as such. Ratings are a visual assessment only; nothing was moved, lifted or tested electrically beyond normal access unless stated.

Condition key: **Good** — no significant defects · **Fair** — minor cosmetic wear, serviceable · **Poor / Attention** — defect or item needing action · **Partial evidence** — surface documented from wide-angle/video only; a dedicated close-up is advised at outgoing. Cleanliness key: **Clean** / **Marks** / **Soiled**.

Meters & services (record on site at ingoing)

Item	Reading / detail	Reference / notes
Electricity meter	_____	Prepaid (Econ unit); DB board & meter photographed.
Water meter	_____	Municipal; locate at boundary.
Gas	_____	Smeg hob is gas — confirm bottle location & level.
Geyser / hot water	_____	Electric geyser in garage/laundry roof space.
Rainwater tank	~200L — present, good	Roof-gutter fed; feeds pool/irrigation.

Readings are recorded on site at handover; photograph each meter face alongside this table.

Keys, remotes & access (record on site)

Item	Reading / detail	Reference / notes
------	------------------	-------------------

Front / pedestrian gate	Keys: ___ Remote: ___	Motorised wood-clad sliding gate.
Garage door	Remote: ___	Automated motor — photographed.
Security trellis / burglar gates	Keys: ___	Rear trellis gate; burglar bars throughout.
Alarm / electric fence	Code held by: ___	Electric perimeter fence + DSC alarm panel.
House / door keys	Sets handed over: ___	Confirm count with tenant at handover.

Safety & detectors

Item	Reading / detail	Reference / notes
Smoke / CO detectors	Observed: none noted	Recommend confirming/installing before tenancy — landlord to verify.
Electric fence	Present — good (visual)	Confirm energiser compliance certificate.
Security	Burglar bars, trellis & motor gate — good	
Gas appliance	Smeg gas hob	Confirm gas CoC on file.
Electrical	DB board photographed	Confirm valid Electrical CoC on file.

Safety items are noted from visual inspection only and are not a compliance certificate.

Coverage summary

Every room below has direct photographic evidence of its ceilings, walls, floors, windows, cupboards and fittings — from dedicated photos and, where needed, targeted walkthrough-video stills. Any remaining **Partial** mark denotes a surface shown only in wide-angle/video, where a dedicated close-up is advised at outgoing.

Room	Imgs	Ceiling	Walls	Floor	Windows	Cupboards	Fittings
Garage / laundry & storage	13	Full	Full	Full	Full	Full	Full
Kitchen	24	Full	Full	Full	Full	Full	Full
Lounge / dining	23	Full	Full	Full	Full	—	Full
Main bedroom suite	23	Part	Full	Full	Full	Full	Part
Bedroom 2	14	Full	Full	Full	Full	Full	Full
Second bathroom	12	Full	Full	Full	Full	—	Part
Guest powder room	1	Part	Full	Full	Full	—	Part

Full — direct photographic evidence **Part** — wide-angle / video only, close-up advised — not applicable

1. Garage / laundry & storage

13 images


Surface / element	Condition	Cleanliness	Notes / evidence
Garage floor & door	Good	Clean	No significant defects noted (visual).
Laundry connections	Good	Clean	No significant defects noted (visual).
Storage units	Good	Clean	No significant defects noted (visual).
Ceiling	Good	Clean	No significant defects noted (visual).
Walls	Good	Clean	No significant defects noted (visual).
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	No significant defects noted (visual).
Power points / switches	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]

Tenant comment: _____

Surface detail — walkthrough-video stills



Garage — ceiling, walls & floor (walkthrough still)



Garage door motor & fitting (walkthrough still)


Photographs



20260720_100307.jpg



20260720_100310.jpg



20260720_100315.jpg



20260720_100403.jpg



20260720_100408.jpg



20260720_100424.jpg



20260720_100435.jpg



20260720_100442.jpg



20260720_100448.jpg



20260720_100454.jpg



20260720_100507.jpg

2. Kitchen

24 images

Surface / element	Condition	Cleanliness	Notes / evidence
Ceiling	Good	Clean	No significant defects noted (visual).
Walls	Good	Clean	No significant defects noted (visual).
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	No significant defects noted (visual).
Power points / switches	Good	Clean	No significant defects noted (visual).
Built-in units & counters	Good	Clean	No significant defects noted (visual).
Sink & taps	Good	Clean	No significant defects noted (visual).
Splashback / tiling	Good	Clean	No significant defects noted (visual).

Tenant comment: _____

Surface detail — walkthrough-video stills



Ceiling line, splashback & power points (walkthrough still)



Upper cupboard interiors (walkthrough still)

Photographs



20260720_095700.jpg



20260720_095706.jpg



20260720_095710.jpg



20260720_095712.jpg



20260720_095719.jpg



20260720_095727.jpg



20260720_095732.jpg



20260720_095742.jpg



20260720_095748.jpg




20260720_095802.jpg




20260720_095815.jpg



20260720_095823.jpg



20260720_095834.jpg



20260720_095849.jpg



20260720_095859.jpg



20260720_095918.jpg



20260720_095922.jpg



20260720_095927.jpg



20260720_095934.jpg



20260720_095941.jpg



20260720_095952.jpg



20260720_095957.jpg


3. Lounge / dining

23 images

Surface / element	Condition	Cleanliness	Notes / evidence
Ceiling	Good	Clean	No significant defects noted (visual).
Walls	Good	Clean	No significant defects noted (visual).
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	Cast-iron fireplace present; functional status not verified — confirm before use.
Power points / switches	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]

Tenant comment: _____

Surface detail — walkthrough-video stills



Ceiling, cornice & downlights (walkthrough still)



Window head & reveal (walkthrough still)

Photographs



20260720_093021.jpg



20260720_093148.jpg



20260720_093153.jpg



20260720_093355.jpg



20260720_093420.jpg



20260720_093539.jpg



20260720_093545.jpg



20260720_093555.jpg



20260720_093601.jpg



20260720_093616.jpg



20260720_093800.jpg



20260720_100151.jpg



20260720_100155.jpg




20260720_100206.jpg



20260720_100221.jpg



20260720_100227.jpg




20260720_100236.jpg




20260720_100241.jpg



20260720_100248.jpg



20260720_100255.jpg



20260720_100259.jpg

4. Main bedroom suite

23 images

Surface / element	Condition	Cleanliness	Notes / evidence
Ceiling	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Walls	Good	Clean	No significant defects noted (visual).
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Power points / switches	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Built-in wardrobe (interior)	Good	Clean	No significant defects noted (visual).
En-suite: basin & vanity	Good	Clean	No significant defects noted (visual).
En-suite: shower / WC	Good	Clean	No significant defects noted (visual).
Wet-area tiling	Good	Clean	No significant defects noted (visual).

Tenant comment: _____

Surface detail — walkthrough-video stills



En-suite — vanity, basins & mirror (walkthrough still)



En-suite — vanity, WC & floor (walkthrough still)

Photographs



20260720_095204.jpg



20260720_095318.jpg



20260720_095321.jpg



20260720_095325.jpg



20260720_095330.jpg



20260720_095341.jpg



20260720_095345.jpg



20260720_095402.jpg



20260720_095410.jpg



20260720_095418.jpg



20260720_095422.jpg



20260720_095428.jpg



20260720_095436.jpg



20260720_095440.jpg



20260720_095448.jpg



20260720_095505.jpg




20260720_095516.jpg




20260720_095536(0).jpg



20260720_095536.jpg



20260720_095544.jpg



20260720_095551.jpg


5. Bedroom 2

14 images


Surface / element	Condition	Cleanliness	Notes / evidence
Ceiling	Good	Clean	No significant defects noted (visual).
Walls	Fair	Clean	Minor cosmetic scuff/mark — normal wear; touch-up recommended.
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	No significant defects noted (visual).
Power points / switches	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Built-in wardrobe (interior)	Good	Clean	No significant defects noted (visual).

Tenant comment: _____

Surface detail — walkthrough-video stills




Ceiling, cornice, downlight & window (walkthrough still)




Built-in wardrobe interior (walkthrough still)

Photographs



20260720_095608.jpg



20260720_095616.jpg



20260720_095622.jpg




20260720_095627.jpg



20260720_095635.jpg



20260720_095647.jpg



20260720_100740.jpg



20260720_100745.jpg



20260720_100808.jpg



20260720_100811.jpg



20260720_100822.jpg



20260720_100824.jpg


6. Second bathroom

12 images


Surface / element	Condition	Cleanliness	Notes / evidence
Ceiling	Good	Clean	No significant defects noted (visual).
Walls	Good	Clean	No significant defects noted (visual).
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Power points / switches	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Sanitaryware (bath / basin / WC)	Good	Clean	No significant defects noted (visual).
Wet-area tiling	Good	Clean	No significant defects noted (visual).
Vanity & mirror	Good	Clean	No significant defects noted (visual).

Tenant comment: _____

Surface detail — walkthrough-video stills



Ceiling & upper wall (walkthrough still)



Wall tiling & fittings (walkthrough still)

Photographs




20260720_100004.jpg



20260720_100030.jpg




20260720_100041.jpg



20260720_100046.jpg



20260720_100058.jpg




20260720_100106.jpg



20260720_100116.jpg



20260720_100125.jpg



20260720_100132.jpg



20260720_100137.jpg

7. Guest powder room

1 images

Surface / element	Condition	Cleanliness	Notes / evidence
Ceiling	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Walls	Good	Clean	No significant defects noted (visual).
Floor	Good	Clean	No significant defects noted (visual).
Skirtings / trim	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Door(s) & frames	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Window(s) & glazing	Good	Clean	No significant defects noted (visual).
Window coverings	Good	Clean	No significant defects noted (visual).
Light fittings	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Power points / switches	Good	Clean	No significant defects noted (visual). [Partial — close-up advised]
Basin & vanity	Good	Clean	No significant defects noted (visual).
WC	Good	Clean	No significant defects noted (visual).
Tiling	Good	Clean	No significant defects noted (visual).

Tenant comment: _____

Photographs



20260720_100214.jpg

Declaration & disclaimer

This schedule of condition records the visual condition and cleanliness of the property and its surfaces and fixtures as observed and photographed by AssetProof on the inspection date. It is not a survey, valuation or structural/compliance report and does not certify electrical, gas, plumbing or fire compliance. Items were not moved, lifted or dismantled, and services were not tested beyond normal visual access. Both parties should review this report against the property before occupation and record any disagreement in writing within the agreed period (typically 7 days); absent written objection it is taken as an agreed record of the ingoing condition.

Overall cleanliness at ingoing: **Clean throughout — presented in good order** (pool excepted, noted under Pool courtyard).

Inspector (AssetProof)

Landlord / Managing agent

Tenant

Name:

Date:

Name:

Date:

Name:

Date: