

INCOMING CONDITION REPORT

Move-In Condition Report

A dated, photo-backed joint inspection at handover — the record that settles the deposit fairly at move-out.

PROPERTY

Green Point, Cape Town

INSPECTION

Incoming (move-in)

DATE

10 June 2026

MANAGING AGENT

[Agency name]



1 Inspection Details

Property	Green Point Apartment, Green Point	Inspection type	Incoming / in-going
Tenant	[Tenant name]	Landlord	[Owner name]
Managing agent	[Agency name]	Inspection date	10 June 2026
Furnishing	Fully furnished	Record basis	Joint walkthrough + photographs

2 Summary

6 AREAS INSPECTED	Good OVERALL CONDITION	2 ITEMS TO NOTE	48 PHOTOS ON FILE
-----------------------------	----------------------------------	---------------------------	-----------------------------

3 Condition by Area

AREA	CONDITION	NOTES (FAIR WEAR VS DAMAGE)
Lounge & living	GOOD	Clean, well-presented. Light fair wear to sofa cushions — noted, not damage.
Kitchen	GOOD	Appliances present and clean. Worktops and cabinetry sound.
Main bedroom	GOOD	Clean; linen present. Headboard and fittings sound.
Second bedroom	GOOD	Clean and sound.
Bathrooms	NOTE	Clean. Minor silicone wear at one shower — recorded as existing at move-in.
Outdoor & pool	GOOD	Terraces, pool and braai in working order. Decking shows normal weathering.

4 Furnished Inventory (key items)

ITEM	QTY	CONDITION
Lounge suite (sectional sofa)	1	GOOD
Dining setting (outdoor)	1	GOOD
Beds + mattresses	2	GOOD
Major appliances (fridge, oven, dishwasher, washer)	4	GOOD
TV + media	1	GOOD

ITEM	QTY	CONDITION
Crockery, glassware, cutlery (sets)	1	GOOD

5 Photographic Record (at move-in)

 Lounge — overall condition IMG 130814.jpg	 Kitchen — fittings & appliances IMG 130937.jpg	 Main bedroom IMG 130828.jpg
 Bathroom IMG 133055.jpg	 Outdoor terrace & pool IMG 130805.jpg	 Terrace & view IMG 130802.jpg

6 Existing Defects Recorded at Move-In

ITEM	CLASSIFICATION	NOTE
Sofa cushion softening	FAIR WEAR	Pre-existing — tenant not liable
Shower silicone wear (main bath)	FAIR WEAR	Pre-existing — recorded for move-out

7 Acknowledgement

PARTY	NAME	SIGNATURE	DATE
Tenant			
Managing agent			
Landlord (if attending)			

Prepared by AirProperty for the managing agent, landlord and tenant. A condition record based on a joint walkthrough and photographs on the date shown — not a valuation or a structural/compliance survey. Fair wear and tear is distinguished from damage to the best assessment from available evidence. At move-out, the same record produces a matching Outgoing report comparing each area against this baseline.