


Figure 22



Sanitized dashboard close-up showing the silicon-diode result and the three-point Source Test fit that produced a negative resistance and therefore requires validation.