

Near miss Report

Project Name: Gainwell	Place of Origin: In front of GCPL Office
Department: Maintenance	Status : Closed
Date of Incident: 22/09/22	Time of Incident: 02:15 PM
Mark all appropriate Conditions: <input checked="" type="checkbox"/> Near-Miss <input type="checkbox"/> Safety Concern <input type="checkbox"/> Safety Suggestion <input type="checkbox"/> Others (Describe):	Type of Concern: <input type="checkbox"/> Unsafe Act <input checked="" type="checkbox"/> Unsafe Condition <input type="checkbox"/> Unsafe Condition of Equipment <input type="checkbox"/> Others(Describe):
Describe the potential Incident/hazard/concern and possible outcome (In detail as possible):- During lunch time Mr. Ashish Sasmal was washing his hand in wash basin near GCPL main office he is applied wash basin water lever paddle this time his right Leg foot got slipped from basin lever foot paddle due to no grips of paddle foot rest plate and paddle lower mounting bolts hole in large paddle tilted .No injury occurred.	
Root Cause for Incident:- No good grips of paddle foot rest plate and paddle lower mounting bolts hole in large paddle tilted	
Corrective Action : -Immediate advice to not use the this wash basin and also advice to immediate rectification of leg foot paddle with proper grip plate.	
Communicated the incident with all our team during TBM & WhatsApp group.	
Near miss E-proc No. CNM002455535	
Reported By:- Mr. Suraj shaw	Date Reported:- 22.09.2022

