



Monthly Maintenance Report

Estates & Facilities

Prepared by the Maintenance Team

A Note from the Maintenance Team

Welcome to the very first edition of our monthly maintenance update! The idea behind these reports is to give staff, managers, and anyone who's ever wondered "*what does the maintenance team actually do all day?*" a proper window into the work being carried out across the site each month. The big, the small, and the occasionally baffling — we'll cover it all. We hope you find it useful, and perhaps even mildly entertaining.

1. Maintenance Jobs Overview

March was a busy one! The team logged and processed **39 job requests** (JS2966–JS3004) across the site — covering everything from hoists and washing machines to oven repairs, mysterious ceiling lights, and at least one very dramatic check engine warning light.

Status	Jobs
✓ Completed	21
■ In Progress	7
■ Waiting on Parts	2
★ New / Queued	9
Total	39

A solid in-month completion rate, with the remainder actively in hand — not bad for a month that also involved some significant project work!

Full Jobs List — March 2026

Job No	Location	Description	Status	Priority
JS2966	Reception Area	Window reflective film — blind replacement	■ Waiting Parts	Moderate
JS2967	Physio Therapy Office	Hoist not working	✓ Complete	Moderate
JS2968	Hannahwood Mews	Ceiling light flashing	■ Waiting Parts	High
JS2969	Hayward	MW hoist down button not working	✓ Complete	High
JS2970	Gilleys	Washing machine leaking	✓ Complete	Low
JS2971	Hannahwood Mews	Washing machine grinding noise on spin	✓ Complete	Low
JS2972	Arthur	Pump making loud noise	✓ Complete	Moderate
JS2973	Hannahwood Mews	O bed — feet not responding on controller	✓ Complete	High
JS2974	Hannahwood Mews	Pad bin lid not working	✓ Complete	High
JS2975	Arthur	Laundry washing machine stuck / not opening	■ In Progress	High

Job No	Location	Description	Status	Priority
JS2976	Newberry	Doorbell not working	✓ Complete	Moderate
JS2977	Hannahwood Mews	PW hoist not holding charge	✓ Complete	High
JS2978	Hayward	AG hoist not charging at charging point	✓ Complete	High
JS2979	Hayward	Hoist not working (lounge)	✓ Complete	Moderate
JS2980	Newberry	Kitchen heating actuator fault	■ In Progress	High
JS2981	Physio Therapy Office	Move Kallax unit to gym	✓ Complete	Low
JS2982	Physio Therapy Office	Shelving in back section of Jack's old office	✓ Complete	Low
JS2983	Other	Removal of chairs	■ In Progress	Moderate
JS2984	Other	Metal cabinets & shelving relocation	■ In Progress	Low
JS2985	Physio Therapy Office	Washing up liquid for physio gym	✓ Complete	Low
JS2986	Gilleys	Tumble dryer making noise	■ In Progress	Moderate
JS2987	Arthur	Oven not working	✓ Complete	High
JS2988	Hannahwood Mews	Hoist yellow button stopping intermittently	✓ Complete	High
JS2989	Hannahwood Mews	Female hydro changing room radiator banging	■ In Progress	High
JS2990	Vehicles	JUMBO check engine warning light	✓ Complete	Moderate
JS2991	Newberry	Paper towel dispenser key broken	✓ Complete	High
JS2992	Hannahwood Mews	Light switch cover	★ New	High
JS2993	Hayward	Curtains for Hayward	★ New	Moderate
JS2994	Hannahwood Mews	Fire door — loose hinges, door rubbing frame	✓ Complete	High
JS2995	Arthur	Appliance tripping kitchen circuit overnight	★ New	High
JS2996	Arthur	Replacement washing machine	★ New	Moderate
JS2997	Arthur	Exposed electrical wires (former light switch)	★ New	Moderate
JS2998	Hannahwood Mews	Sink blocked — D&D; shared bathroom	★ New	High
JS2999	Hannahwood Mews	Bed too low for staff — manual handling concern	■ In Progress	High
JS3000	Hannahwood Mews	Bed side rails very hard to lift	★ New	High
JS3001	Newberry	Window handle broken	✓ Complete	High
JS3002	Newberry	Picture to hang in bedroom	★ New	Low
JS3003	Hannahwood Mews	COSHH cupboard lock / fittings	★ New	Moderate
JS3004	Hayward	DK hoist not charging properly	✓ Complete	High

Notable Completions This Month

Hoists — Hayward & Hannahwood Mews (JS2967, JS2969, JS2977, JS2978, JS2979, JS2988, JS3004)

Seven hoist faults across Hayward and Hannahwood Mews this month — charging issues, sticky buttons, down buttons refusing to respond, and controls that had simply decided they'd had enough. All resolved and back in full working order. Keeping people moving is, after all, rather the point.

Fire Door — Hannahwood Mews (JS2994)

A fire door at Mews had developed a lean — hinges loose, door rubbing against the frame. Hinges tightened, door is now standing proud and doing its job properly.

Oven — Arthur (JS2987)

No more cold suppers at Arthur. The oven was down, investigated, and fixed.

Washing Machine — Gilleys (JS2970)

A leaking washing machine at Gilleys was swiftly attended to. Dried out (entirely pun intended) and sorted.

Doorbell & Window Handle & Paper Towel Dispenser — Newberry (JS2976, JS3001, JS2991)

Doorbell back in action, window handle replaced, paper towel dispenser key sorted.

Vehicles — JUMBO Check Engine Light (JS2990)

JUMBO's dashboard lit up like a Christmas tree. Investigated, issue identified and resolved.

O Bed & Pad Bin — Hannahwood Mews (JS2973, JS2974)

O bed feet not responding on controller — sorted. Pad bin lid — sorted.

Pump — Arthur (JS2972)

Loud pump at Arthur investigated and sorted. Peace restored.

Physio & Therapy Suite Reorganisation (JS2981, JS2982, JS2985)

Kallax unit relocated to gym, shelving put up in Jack's old office — and yes, washing-up liquid for the physio gym was sorted too.

In Progress

- **Newberry — Kitchen Heating Actuator Fault (JS2980)**
- **Hannahwood Mews — Bed Height Adjustment (JS2999)**
- **Gilleys — Tumble Dryer (JS2986):** Making quite a racket during use.
- **Hannahwood Mews — Female Hydro Changing Room Radiator (JS2989):** Banging radiator under investigation.
- **Metal Cabinets & Shelving Relocation (JS2984)**
- **Arthur — Laundry Washing Machine (JS2975):** Machine stuck and not opening.
- **Removal of Chairs (JS2983)**

Waiting on Parts:

- **Flashing ceiling light — Hannahwood Mews (JS2968):** Parts ordered.
- **Window reflective film — Reception Area (JS2966):** Emily, we absolutely have not forgotten. Parts are on their way.

New Jobs Logged — Queued for Action (9 jobs)

- Arthur — Exposed Electrical Wires (JS2997): Cover to be fitted. Electrician aware.
- Arthur — Appliance Tripping Kitchen Circuit (JS2995): Trip switch blowing overnight. Investigating.
- Arthur — Replacement Washing Machine (JS2996): Related to above.
- Hannahwood Mews — Sink Blockage (JS2998): D&D shared bathroom. On the list.
- Hannahwood Mews — COSHH Cupboard Lock (JS3003): Fittings need attention. Padlock in place.
- Hannahwood Mews — Bed Side Rails (JS3000): Very hard to lift on both beds.
- Hannahwood Mews — Light Switch Cover (JS2992)
- Hayward — Curtains (JS2993)
- Newberry — Picture to hang (JS3002): Low priority.

2. Compliance

All five statutory and routine checks were completed on schedule this month — a full house.

Compliance Activity	Status
Fire Alarm Testing	✓ Complete
Emergency Lighting Testing	✓ Complete
Fire Extinguisher Checks	✓ Complete
Water Temperature Checks	✓ Complete
Legionella Testing	✓ Complete

3. Projects

Blachford — Final Works Complete

We're delighted to say that the final works at Blachford are now **finished**, and the space looks absolutely *fantastic*. It has been a real transformation and a huge well done to everyone involved — both from the maintenance side and beyond.

Hydropool — Major Refurbishment Underway

This month has seen the start of a significant and long-overdue investment in our Hydropool. The team has thrown itself into it (*not literally — the pool is currently out of action*).

★ Pool Filter Removal & Replacement — The Single Biggest Cost in the Project

The pool filter has been cut apart and removed, and a full replacement is now underway. This is, without question, **the most significant item — both in terms of effort and cost — in the entire Hydropool refurbishment.**

The existing filter was a large, aging vessel packed with *literally tonnes of sand*. Extracting it was a considerable undertaking and the team did a brilliant job getting it out safely. Replacing this filter is the central investment that allows the Hydropool to function properly and efficiently for years to come.

All other works — the flooring, the grates, the changing rooms — are important, but the **filter replacement is the backbone of the whole project**. It represents a major financial commitment by the Trust and reflects how seriously we take the long-term quality of this facility.

Old Crumb Flooring Removed

The tired red crumb flooring around the pool has been lifted and taken away. The new floor colour is already a huge improvement — much brighter and far more pleasant to look at.

Grates Removed

The grates surrounding the pool have been taken out, ready to be fully renewed.

Pool Changing Rooms

Refurbishment work on the pool changing rooms is also underway and will continue over the coming weeks.

The Hydropool is a hugely valued part of what Dame Hannah offers, and this level of investment reflects the Trust's commitment to keeping it in the best possible condition — not just for today, but for the long term.

Looking Ahead to April

There's plenty in the pipeline! The Hydropool refurbishment — particularly the filter replacement — will continue in earnest, we'll be working through the job queue, and compliance checks will roll on as normal.

As ever, if you spot something that needs attention, please log it on the job system — no job too big, no job too small (*although we will raise an eyebrow at the one asking for washing-up liquid*).

*Thank you to all staff for logging jobs promptly and for your patience while we work through the queue.
Feedback on format or content is always welcome.*