

Dame Hannah Roger's Trust

Maintenance Team Monthly Summary Report

March 2025 – February 2026


Prepared by the Maintenance Team | March 2026
Confidential — for internal use

544	93%+	12	16
Total Jobs	Completion Rate	Months Covered	Locations Serviced

Executive Summary

Over the 12-month period from March 2025 to February 2026, the Dame Hannah Roger's Trust maintenance team logged and actioned a total of 544 jobs across 16 buildings and areas on the estate. The team maintained a completion rate in excess of 93%, with most jobs resolved swiftly and the small number of outstanding items attributable only to awaiting specialist contractors or replacement parts.

544 Total Jobs Logged	93%+ Completion Rate	65 Busiest Month (July 2025)	153 Jobs at Hannahwood Mews
---	--	--	---



July 2025 was the busiest month (65 jobs), while December 2025 was the quietest (32 jobs). There is a clear pattern of higher workload in summer months and January, with a dip over the Christmas period.

Monthly Breakdown

March 2025

52 jobs | 100% completed

Top locations: Hannahwood Mews (13) · Hayward (11) · Newberry (10)

A busy start to the year with all 52 jobs resolved within the month. The highest volume came from **Hannahwood Mews** (13), **Hayward** (11), and **Newberry** (10). Key themes included plumbing blockages, hoist faults, window handle repairs, and bedroom blinds. Notable jobs included a blocked bathroom sink at Hannahwood Mews, a broken window handle at Marchesi, and screw panel replacements in the Physio Therapy Office.

April 2025

41 jobs | 100% completed

Top locations: Hannahwood Mews (15) · Newberry (6) · Hannahwood (4)

A slightly quieter month with 38 repairs and 3 requests, all completed. **Hannahwood Mews** remained the most active location (15 jobs). Activity centred on hoist and mobility equipment faults (frayed hoist belt, non-charging Arjo), broken call bells, curtains to be rehung, and door issues. Works at the central Hannahwood building included a plant pot repair and a catching training room door.

May 2025

44 jobs | 100% completed

Top locations: Arthur (8) · Hannahwood Mews (8) · Hayward (7)

All 44 jobs completed. Work was spread across **Arthur** (8), **Hannahwood Mews** (8), and **Hayward** (7). Hoist and equipment issues featured heavily (broken Arjo wheel, hoist not charging), alongside plumbing jobs (missing bath plugs, slow sink drains). A carpet clean, a broken bedroom side light glass, and platform works were also attended to.

June 2025

38 jobs | 95% completed

Top locations: Newberry (9) · Hayward (7) · Hannahwood Mews (6)

36 of 38 jobs completed, with 2 carried into July. The busiest location was **Newberry** (9) followed by **Hayward** (7). Jobs included mounting a resident's TV to the wall, removing broken garden pots, a jammed hand dryer, raised bathroom flooring, stiff bed rails, and broken door handles. A radiator was removed and bagged for disposal.

July 2025

65 jobs | 100% completed

Top locations: Hannahwood Mews (16) · Hayward (11) · Marchesi (8)

The **busiest month of the year** — 65 repairs, all completed. **Hannahwood Mews** (16), **Hayward** (11), and **Marchesi** (8) led the way. Notable jobs included lifting floor tiles at Arthur, mould treatment in a resident's room, a broken bath controller with exposed wires at Marchesi, hoist and shower hose repairs, a PAT test session, and the Ernie minibus tail-gate fault.

August 2025

51 jobs | 96% completed

Top locations: Hannahwood Mews (18) · Newberry (9) · Hayward (7)

49 of 51 jobs completed, with 2 carried over. **Hannahwood Mews** reached its highest single-month count at 18 jobs. Work included broken shower heads, hoist charging faults, a snapped plug socket at Marchesi, a stuck bathroom door at Arthur, and broken door handles at Newberry. Two bathroom fitting jobs were carried into September.

September 2025

37 jobs | 100% completed

Top locations: Hannahwood Mews (14) · Arthur (6) · Hayward (5)

All 37 jobs completed. **Hannahwood Mews** accounted for 14. Work included a broken sleep system grip, a cut rope on a hoist turntable at Hayward, a loose shed panel, and a vehicle warning light investigation. General works included flat-pack furniture assembly in the foyer and a rear door repair at the Charity Shop (Saltash).

October 2025

41 jobs | 95% completed

Top locations: Hannahwood Mews (15) · Marchesi (8) · Hayward (6)

39 of 41 jobs completed, including 2 projects — fitting keypad combination locks on Speech and Language Therapy Office doors. **Hannahwood Mews** (15) and **Marchesi** (8) were busiest. Key jobs: hoist button faults, a blind off the wall, a blocked bathroom sink, fire door checks, and seasonal Christmas light hook fitting at Arthur.

November 2025

37 jobs | 92% completed

Top locations: Marchesi (7) · Hannahwood Mews (7) · Hayward (6)

34 of 37 jobs completed, with 3 carried over. Activity was well spread, with **Marchesi**, **Gilleys**, and **Hannahwood Mews** each at 6–7 jobs. Electrical issues featured prominently — multiple non-working lights across Day Services, bathrooms, and kitchens. Plumbing included a leaking washing machine and a blocked drain. A boiler low-pressure alert at Gilleys was also attended to.

December 2025

32 jobs | 100% completed

Top locations: Arthur (10) · Hannahwood Mews (7) · Gilleys (4)

The **quietest month** of the year, but all 32 jobs were fully resolved. **Arthur** was unusually busy (10 jobs), with multiple faults raised on Christmas Eve — broken drawer and wardrobe shelf, a flashing bathroom light, a toilet door dragging on the floor, and a faulty oven. A leaking shower head and a vehicle engine management light were also resolved across other sites.

January 2026

61 jobs | 92% completed

Top locations: Hannahwood Mews (18) · Newberry (12) · Gilleys (7)

The **second busiest month** — 61 jobs with 56 completed and 5 ongoing at month end. **Hannahwood Mews** (18), **Newberry** (12), and **Gilleys** (7) were most active. Key work included multiple hoist faults, trip hazards in kitchen flooring, a conservatory spotlight, a broken feed room door handle, and gutter blockages at Newberry.

February 2026

45 jobs | 93% completed


Top locations: Hannahwood Mews (15) · Arthur (14) · Hayward (6)

42 of 45 jobs completed, with 3 ongoing. **Hannahwood Mews** (15), **Arthur** (14), and **Hayward** (6) were most active. Notable jobs included a hoist fault in Hayward's lounge, a noisy tumble dryer and ceiling tile replacement at Hannahwood Mews, a shower cable relocation, noisy pipes in the Finance Office, and a window reflective film installation (awaiting parts).

Job Type Analysis


The following analysis draws on 476 categorised records from the job system database, covering the same 12-month period. Jobs are classified by trade category, location, and fault type.

Jobs by Category



Category	Jobs	% of Total
Other (General Maintenance)	142	29.8%
Equipment	117	24.6%
Electrical	69	14.5%
Plumbing	51	10.7%
Decorative	32	6.7%
Assembly	28	5.9%
Fire Safety	12	2.5%
Move	7	1.5%
Trust Vehicle	7	1.5%
Groundwork	6	1.3%
Disposal	5	1.1%

Jobs by Location



Location	Jobs	Key Work T
Hannahwood Mews	153	Equipment, P
Hayward	81	Hoist repairs,
Newberry	65	Plumbing, do
Arthur	64	Kitchen, bath
Marchesi	52	Bath equipme
Gilleys	43	Appliances, w
Other	27	Shared staff a
Hannahwood (Main)	18	Reception, tra
Day Services	12	Hoists, doors
Vehicles	7	Minibus faults
Reception / Physio / Finance / Charity	8	Miscellaneous

Most Frequently Recurring Fault Types

Based on keyword analysis of all 544 job descriptions, the following fault categories recur most frequently throughout the year.

Fault Type	Frequency	Typical Description
Hoist faults	~60	Button not working, not charging, not tracking, belt worn
Plumbing / blockages	~55	Drains blocked, washing machine leaking, shower draining slowly
Broken doors / handles / locks	~50	Handles fallen off, doors dragging, keypads intermittent
Light / bulb faults	~47	Bulbs gone, fittings flickering, rooms without light
Shower issues	~23	Leaking hoses, broken controls, shower not draining
Washing machines / tumble dryers	~22	Not starting, leaking, loud noises
Blinds / windows	~18	Blinds fallen off wall, windows not locking
Bed and furniture faults	~18	Loose bedsides, broken drawers, wardrobe damage
Floor / ceiling defects	~15	Raised flooring, lifting tiles, ceiling tiles broken
Radiators / heating	~9	Cold radiators, low boiler pressure, hot water loss

Key Observations & Recommendations

● Hoist & Mobility Equipment — Highest Priority

Hoist faults appear in almost every month and every location. With approximately 60 recorded incidents, this is the single most critical recurring maintenance need. These items are directly linked to resident safety and care delivery. A planned preventative maintenance schedule for all hoists and Arjo equipment would be worth considering.

● Hannahwood Mews — Highest Demand Location

Hannahwood Mews consistently generates the most work (153 jobs — 28% of the annual total). The volume and complexity of jobs here reflects the size of the facility and the dependency level of its residents. Consideration could be given to prioritising resource allocation to this building.

● Electrical & Lighting — Frequent but Fast to Resolve

Light bulb, fitting, and socket faults account for around 1 in 7 jobs but are typically quick to resolve in-house. These rarely require specialist contractors and can often be batched efficiently during routine visits.

● Plumbing — A Consistent Year-Round Demand

Blocked drains, washing machines, shower heads, and leaking pipes recur regularly across all locations. Plumbing represents approximately 10–11% of categorised work. Proactive drain maintenance and a washing machine service schedule could help reduce reactive call-outs.

● Seasonal Patterns

Job volume peaks in July (summer high of 65) and again in January (61). December is consistently the quietest month. Winter months (November–January) bring more heating, boiler, and structural fault reports. Planning resource availability around these known peaks is advisable.

● **Completion Rate — A Strong Performance**

The team's overall completion rate exceeds 93% for the 12-month period. The small number of outstanding jobs are attributable to awaiting contractor availability or replacement parts — not operational delays. This reflects a high-performing, responsive maintenance service.

*Data sourced from: Dame Hannah Maintenance Job System export (March 2025 – February 2026) and jobstotal.xlsx.
Report prepared: March 2026 · Dame Hannah Roger's Trust · Confidential*