



Monthly Maintenance Report

Estates & Facilities

Prepared by the Maintenance Team

A Note from the Maintenance Team

Welcome to the very first edition of our monthly maintenance update! The idea behind these reports is to give staff, managers, and anyone who's ever wondered "*what does the maintenance team actually do all day?*" a proper window into the work being carried out across the site each month. The big, the small, and the occasionally baffling — we'll cover it all. We hope you find it useful, and perhaps even mildly entertaining.

1. Maintenance Jobs Overview

March was a busy one! The team logged and processed **35 job requests** across the site — covering everything from hoists and washing machines to oven repairs, mysterious ceiling lights, and at least one very dramatic check engine warning light.

Status	Jobs
✓ Completed	21
■ In Progress	7
■ Waiting on Parts	2
★ New / Queued	5

A completion rate of around 60% in-month, with the remainder actively in hand — not bad for a month that also involved some major project work (more on that below)!

Notable Completions This Month

Hoists — Hayward & Hannahwood Mews

There was clearly something in the water this March, because hoists were the theme of the month. We dealt with multiple hoist faults across Hayward and Hannahwood Mews — charging issues, sticky buttons, and controls that had simply decided they'd had enough. All resolved and back in full working order. Keeping people moving is, after all, rather the point.

Fire Door — Hannahwood Mews (JS2994)

A fire door at Mews had developed a lean — hinges loose, door rubbing against the frame, and making a nuisance of itself every time someone tried to close it. Hinges tightened, door is now standing proud and doing its job properly.

Oven — Arthur (JS2987)

No more cold suppers at Arthur. The oven was down, it was investigated, it was fixed. Everyone's dinners are warm again and order is restored.

Washing Machine — Gilleys (JS2970)

A leaking washing machine at Gilleys was swiftly attended to. Dried out (entirely pun intended) and sorted.

Doorbell — Newberry (JS2976)

Ding dong! Newberry's doorbell was silent for a spell. It's back in action and announcing visitors once more.

Window Handle & Paper Towel Dispenser — Newberry (JS3001, JS2991)

A broken window handle was replaced — simple, quick, done. The paper towel dispenser key was also sorted; as it turned out, it was the only key we ever had. A practical solution was found and it's back in use.

JUMBO Check Engine Light (JS2990)

JUMBO's dashboard lit up like a Christmas tree and gave us all a mild moment of panic. Investigated, issue identified and resolved. JUMBO lives to fight another day.

Physio & Therapy Suite Reorganisation (JS2981, JS2982)

The team relocated a Kallax unit into the gym and put up shelving in the back section of Jack's old office. The space is looking much tidier and better organised as a result.

In Progress

Several jobs are currently underway and will be completed in the coming days:

- **Newberry — Kitchen Heating Actuator Fault (JS2980):** Work is in progress.
- **Hannahwood Mews — Bed Height Adjustment (JS2999):** Adjustments being made.
- **Gilleys — Tumble Dryer (JS2986):** Making quite a racket during use. Being looked at.
- **Hannahwood Mews — Female Hydro Changing Room Radiator (JS2989):** Banging radiator under investigation.
- **Metal Cabinets & Shelving Relocation (JS2984):** Ongoing move from wheelchair repair room to behind physio gym.
- **Arthur — Laundry Washing Machine (JS2975):** Machine stuck and not opening. In hand.

Waiting on Parts:

- **Flashing ceiling light — Hannahwood Mews (JS2968):** Parts ordered.
- **Window reflective film — Reception Area (JS2966):** Emily, we absolutely have not forgotten about the blinding morning sun. Parts are on their way.

New Jobs Logged — Queued for Action

- **Arthur — Exposed Electrical Wires (JS2997):** Cover to be fitted. Electrician aware.
- **Arthur — Appliance Tripping the Kitchen Circuit (JS2995):** Trip switch blowing overnight. Being investigated.
- **Arthur — Replacement Washing Machine (JS2996):** Requested in connection with above.
- **Hannahwood Mews — Sink Blockage (JS2998):** Shared bathroom sink blocked. On the list.
- **Hannahwood Mews — COSHH Cupboard Lock (JS3003):** Door fittings need attention. Padlock in place.
- **Hannahwood Mews — Bed Side Rails (JS3000):** Top very hard to lift on both beds. Logged.
- **Newberry — Picture to hang (JS3002):** Picture to go up in bedroom. Low priority.

2. Compliance

Compliance checks are the unsung heroes of site management — the behind-the-scenes work that keeps the Trust operating safely, legally, and without nasty surprises. This month, **all five statutory and routine checks were completed on schedule.**

Compliance Activity	Status
Fire Alarm Testing	✓ Complete
Emergency Lighting Testing	✓ Complete
Fire Extinguisher Checks	✓ Complete
Water Temperature Checks	✓ Complete
Legionella Testing	✓ Complete

A full house — everything ticked off and records up to date. Safety isn't optional, but we do try to make it as painless as possible for everyone involved.

3. Projects

Blachford — Final Works Complete

We're delighted to say that the final works at Blachford are now **finished**, and the space looks absolutely *fantastic*. It has been a real transformation, and the result speaks for itself. A huge well done to everyone involved — both from the maintenance side and beyond. It is always wonderful to see what a difference these improvements make to the people who use the spaces every day.

Hydropool — Major Refurbishment Underway

Now, this is the big one. This month has seen the start of a significant and long-overdue investment in our Hydropool — and it's fair to say the team has thrown themselves into it (*not literally — the pool is currently out of action*).

Old Crumb Flooring Removed
The tired red crumb flooring around the pool has been lifted and taken away. The new floor colour is already a huge improvement — much brighter and far more pleasant to look at. First impressions count, even underwater.

Grates Removed
The grates surrounding the pool have been taken out, ready to be fully renewed as part of the wider improvement works. Out with the old, in with the new.

Pool Filter Removed — This One Deserves Its Own Entry

The pool filter has been cut apart and removed. This might sound straightforward, but we should mention that this filter contained literally tonnes of sand — and we do mean that in the most literal sense. It was a substantial undertaking and the team did a brilliant job. This filter was long overdue for replacement and its removal marks a key step in modernising the pool.

Pool Changing Rooms

Refurbishment work on the pool changing rooms is also underway. Improvements are ongoing and will continue over the coming weeks.

The Hydropool is a hugely valued part of what Dame Hannah offers, and this level of investment reflects the Trust's commitment to keeping it in the best possible condition — not just for today, but for the long term.

Looking Ahead to April

There's plenty in the pipeline! The Hydropool refurbishment will continue in earnest, we'll be working through the job queue (including some of those trickier ones), and compliance checks will roll on as normal.

As ever, if you spot something that needs attention, please log it on the job system — no job too big, no job too small (*although we will raise an eyebrow at the one asking for washing-up liquid*). The team is always on hand, always busy, and always grateful for a kind word.

Thank you to all staff for logging jobs promptly and for your patience while we work through the queue. These reports are new — if you have any feedback on format or content, please do let us know.