

Repair Order

	Date of the accident		10/11/2021	Accident No	14311/2021/1
	Vehicle Owner Name		سليمان فائق سليمان	Workshop Detail	Amman مركز عصام عواد,البيادر
	VIN		KNAGN41CBG5098096	Request Number	11112177 /1R
	Plate No		80-9192	Accident Type	
	Car Details		Kia Optima	Third Party Liability	
	Year		2016	Damage Point	1211, 10,
	Created By		فراس الاخرس	PO Note	-
	(11/11/2021 8:51:56 AM)			Pricing Type	
				Pricing and Providing	


Task Details

Type	Labour Price	Labour Time	Task Description	#
Body Repair	300 JOD	4 (Day(s))	تصليب مقدمة غطاء محرك اثر الحادث فحص الواجهة الامامية	1

Ordered Parts

Phone	Supplier	Received On	Quantity	Name	#
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	طمبون امامي (Used)	1
Note : نظام وكالة					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	جناح امامي شمال (Used)	2
Note : نظام وكالة					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	كشاف امامي شمال مع برواز (Used)	3
Note : نظام وكالة					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	حمالات طمبون امامي (Used)	4
Note :					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	ضوء امامي شمال زنون (Used)	5
Note : نظام وكالة					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	بطانة وحل امامي شمال (Used)	6
Note :					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	جسر طمبون امامي مع فليئة (Used)	7
Note :					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	بطانة اسفل الطمبون امامي (Used)	8
Note :					
0797771999	مؤسسة احمد الشيخ لتجارة قطع السيارات	-	1	سيويلر طمبون امامي (Used)	9
Note :					

PO Approved by



PM 1:50 ,11/14/21
ناصر رحالة

