## **Purchase Order**

## PO Approval date

16/11/2021

Date of the accident

02/11/2021

Vehicle Owner Name راما مجد الضمور

**Accident No** 14202/2021/1

VIN

Workshop Detail

KMHDG41DBFU431540

Amman كراج خالد طه ,البيا 3ر4459044590+

Plate No

Request Number

44-40039

11112137 /1R

**Car Details** Hyundai Avante

**Accident Type** 

Year 2015 Third Party Liability

**Created By** 

**PO** Amount

فراس الاخرس (11/11/2021 10:40:13AM)

117 JOD

Pricing Type

**PO Note** 

Pricing and Providing

## **Ordered Parts**

#	Name	Unit Price	Quantity	Net Price	Received On	Supplier
1	طمبون خلفي مع سبويلر ( Used )	108 JOD	1	108 JOD	-	العبسـي لقطع غيار السـيارات
: Note						
2	عاكسة طمبون خلفي شمال يمين ( Used )	9 JOD	1	9 JOD	-	العبسي لقطع غيار السيارات
: Note						

117 JOD

PO Amount