

Repair Order

Accident No

3201asw

Workshop Detail

العقبة, محمود سالم, Aqaba

Request Number

1092219 /1R

Accident Type

complementary

Damage Point

1615, 14, 13, 9, 8, 4, 3,

PO Note

—

Pricing Type

Pricing and Providing

Date of the accident

13/07/2022

Vehicle Owner Name

NN

VIN

32051281981292626262

Plate No

02102

Car Details

Geely Emgrand X7

Year

2018

Created By

(01/09/2022 2:36:43 PM) delta ic

Task Details

Type	Labour Price	Labour Time	Task Description	#
Body Repair	311 JOD	5 (Day(s))	paint the car	1

Ordered Parts

Supplier	Received On	Quantity	Name	#
مزود نظام	-	1	ماتور مساحة خلفي (New (Aftermarket))	1
مزود نظام	-	1	شل امامي (New (Original))	2

PO Approved by

PM 2:52 , 9/1/22

فارس النمري

Approved By

delta ic