Repair Order

Accident No 14202/2021/1 Date of the accident Workshop Detail 02/11/2021 Amman كراج خالد طه,البيادر Vehicle Owner Name راما محد الضمور Request Number 11112137 /1R KMHDG41DBFU431540 Accident Type Plate No Third Party Liability 44-40039 Damage Point Car Details Hyundai Avante PO Note Year 2015 Pricing Type Created By Pricing and Providing فراس الاخرس (AM) 10:40:11 11/11/2021)

Task Details

	Type	Labour Price	Labour Tin	ne Task Description	#
	Body Repair	100 JOD	0 (Day	اصلاح الضربه حسب الاصول	1
		Ordered Part	ts		
Phone	Supplier	Received On	Quantity	Name	#
0777715197	العبسي لقطع غيار السيارات	-	1	طمبون خلفي مع سبويلر (Used)	1
					: Note
0777715197	العبسي لقطع غيار السيارات	-	1	عاكسة طمبون خلفي شمال يمين (Used)	2
					: Note

PO Approved by

11/16/21, 11/16/21 ناصر رحاحلة