



ALL CUSTOMERS.

INSPECTION DATE

All



Select Customer

All



Overall Performance

TRUCK

69%

TRAILER

76%


Fleet Inspected

VehicleType


Number of Vehicle

TRAILERS AIR SUSPENSION	107
TRAILERS MECHANICAL SUSPENSION	64
TRUCKS	112
Total	283

Inspection Trend Line Chart



Distribution of Inspected Vehicles by VehicleType



Compliance Performance

Truck Brake System

61%

Truck Electric System

76%

Battery Inspection

68%

Truck Suspension System

68%

Truck King Pin

64%

Truck Steering Geometry

77%

Air Bag

74%

Axle Assembly

74%

Trailer Brake System

70%

Trailer Electric System

71%

Air Hanger

73%

Mechanical Hanger

73%

Trailer King Pin

89%

Landing Gear


82%

Trailer Air System

82%


Trailer Lights

70%

	
Air Bag	74%
Air Hanger	73%
Axle...	74%
Battery	68%
Brake...	70%
Electric System	71%
Landing Gear	82%
Mech Hanger...	73%
Steering Geometry	77%
Trailer Kin...	89%
Truck Brake...	61%
Truck Electric...	76%
Truck Kin...	64%
Truck Suspensio...	68%
Trailer Ai...	82%
Trailer...	70%

ALL CUSTOMERS.

Fitment Date: 10/11/2019
Last Inspected: 11/9/2022



PARAMETRIC PERFORMANCE

Terminals	Battery Condition
87.10%	61.29%

Year	2022	
FleetID	Terminals	Battery Condition
T 120 BSS	✓	✓
T 386 DVB	✓	✓
T 405 CZP	✗	✓
T 469 DVT	✓	✓
T 568 CRA	✓	✗
T 641DVH	✓	✗
T 686 DYY	✓	✓
T 725 CRT	✓	✓
T 911DMR	✓	✗
T112DNU	✓	✓
T147DNY	✓	✓
T180DYN	✓	✓
T195BTE	✓	✗
T233BFH	✗	✗
T300 CBX	✓	✗
T324CZS	✓	✓
T407DPT	✓	✓
T411DFU	✓	✗
T469DVT	✗	✓
T528BKC	✓	✓
T570DPJ	✓	✓

List of Vehicles

FleetID
AIC 8923
ALJ 7186
ALJ8784T
ALK 6789
ALK 6790
ALK 7420T
ALK 7431 T
HESU 0001
HESU 0004
HESU 0029
HESU 0043
HESU 017
STL 3664
T 101BRZ
T 118DPH
T 120 BSS
T 134 DXS
T 169 DUL
T 175 DUL
T 177AEG
T 181 DYC

Fault Details

FleetID	BATTERY CONDITION
T 568 CRA	DAMAGED 1
T 641DVH	DAMAGED 2
T 911DMR	DAMAGED 2
T195BTE	DAMAGED 2
T300 CBX	DAMAGED 1
T411DFU	DAMAGED 1
T593DVZ	DAMAGED 2
T799DVE	DAMAGED 2
TR 09(T194DAX)	DAMAGED 2
TR 11(T753DEY)	DAMAGED 2
TR 18(T888BWN)	DAMAGED 1



Air Bag

74%

Air Hanger

73%

Axle...

74%

Battery

68%

Brake...

70%

Electric...

71%

Landing...

82%

Mech Hanger...

73%

Steering...

77%

Trailer Kin...

89%

Truck...

61%

Truck Electric...

76%

Truck Kin...

64%

Truck Suspensio...

68%

Truck Kin...

82%

Truck Kin...

70%

ALL CUSTOMERS.

Fleets Inspected Trend

Crank Handle

78.85%

Rubber Cushioned Foot

71.79%

Crank Parking Hook

77.56%

Supporting Tube

89.10%

High Speed Function

83.97%

Reinforcing Members

79.49%

Housing LHS

86.54%

Housing RHS

85.90%

Low Speed Function

83.33%

PARAMETRIC PERFORMANCE

List Of Vehicles

FleetID

AIC 8923

ALJ 7186

ALJ8784T

ALK 6789

ALK 6790

ALK 7420T

ALK 7431 T

HESU 0001

HESU 0004

HESU 0029

HESU 0043

HESU 017

STL 3664

T 101BRZ

T 118DPH

T 120 BSS

T 134 DXS

T 169 DUL

T 175 DUL

T 177AEG

T 184 DXS

T 185 BDN

T 206 CAF

T 237 DPE

T 262 DFC

T 287 DFJ

T 292 DFJ


T 184 DXS

FleetDetailsSummary

FleetID	HIGH SPEED FUNCTION	CRANK HANDLE	HOUSING RHS	RUBBER CUSHIONED FOOT	CRANK PARKING HOOK	HOUSING LHS	REINFORCING MEMBERS	LOW SPEED FUNCTION
T445BKQ	NEED REPAIR	DAMAGED	OK	MISSING	DAMAGED	OK	OK	NEED REPAIR
HESU 0029	OK	MISSING	OK	MISSING	MISSING	OK	Not Inspected	OK
STL 3664	OK	MISSING	OK	OK	OK	OK	OK	OK
T 184 DXS	NEED REPAIR	MISSING	DAMAGED	MISSING	MISSING	DAMAGED	NEED REPAIR	NEED REPAIR
T 419 CMH	NEED REPAIR	MISSING	DAMAGED	OK	MISSING	OK	NEED REPAIR	NEED REPAIR
T 579 BCQ	OK	MISSING	OK	OK	OK	OK	OK	OK
T 619 BUB	NEED REPAIR	MISSING	DAMAGED	MISSING	MISSING	DAMAGED	NEED REPAIR	NEED REPAIR
T 656 AVZ	NEED REPAIR	MISSING	OK	WORN OUT	MISSING	OK	OK	NEED REPAIR
T 803 DQV	NEED REPAIR	MISSING	OK	MISSING	OK	OK	NEED REPAIR	NEED REPAIR
T 947 DAU	OK	MISSING	OK	OK	OK	OK	OK	OK
T189DUD	OK	MISSING	OK	OK	MISSING	OK	OK	OK
T215DFC	OK	MISSING	OK	OK	MISSING	OK	OK	OK
T216DHW	NEED REPAIR	MISSING	OK	MISSING	MISSING	OK	NEED REPAIR	NEED REPAIR

<div><div></div></div>	
Air Bag	74%
Air Hanger	73%
Axle...	74%
Battery	68%
Brake...	70%
Electric...	71%
Landing...	82%
Mech Hanger...	73%
Steering...	77%
Trailer Kin...	89%
Truck...	61%
Truck Electric...	76%
Truck Kin...	64%
Truck Suspensio...	68%
Trailer Ai...	82%
Trailer...	70%

ALL CUSTOMERS.



PARAMETRIC PERFORMANCE

Ball joint	King Pin Bolts	King Pin
82.67%	64.00%	84.00%

List Of Vehicles

Fault Details

Year	2022													
Quarter	Qtr 3							Qtr 4						
Month	August				September			October						November
FleetID	Ball Joint	KPin	KPinBolt	Ball Joint	KPin	KPinBolt	Ball Joint	KPin	KPinBolt	Ball Joint	KPin	KPinBolt	Ball Joint	KPin
ALJ 7186							✓	✓	✓					
ALK 6789							✓	✓	✓					
ALK 6790							✓	✓	✓					
T 120 BSS				✓	✓	✓								
T 361 CGK										✓	✓	✓		
T 384 DVB										✓	✗	✓		
T 386 DVB							✓	✓	✓					
T 460 DSZ				✗	✓	✓								
T 469 DVT				✓	✓	✗								
T 508 CYV														
T 568 CRA				✓	✓	✓								
T 641DVH				✓	✓	✗								
T 645 DNY														✓
T 668DYY				✓	✓	✓								
T 686 DYY				✓	✓	✗								
T 725 CRT				✓	✓	✓								
T 976DVN										✓	✓	✓		
T112DNU				✗	✓	✓								
T133CCU							✗	✗	✗					
T147DNY				✓	✓	✓								
T147DNY														


FleetID
AIC 8923
ALJ 7186
ALJ8784T
ALK 6789
ALK 6790
ALK 7420T
ALK 7431 T
HESU 0001
HESU 0004
HESU 0029
HESU 0043
HESU 017
STL 3664
T 101BRZ
T 118DPH
T 120 BSS
T 134 DXS
T 169 DUL
T 175 DUL
T 177AEG
T 184 DXS
T 185 BDN
T 206 CAF

FleetID	KING PIN
T 384 DVB	DAMAGED
T 508 CYV	WORN OUT
T133CCU	WORN OUT
T279CZA	WORN OUT
T407DPT	WORN OUT
T411DFU	WORN OUT
T632CUB	WORN OUT
T775BLW	WORN OUT
T799DEZ	PLAY
T855DNF	DAMAGED
TR 09(T194DAX)	PLAY

<div><div></div><div></div><div></div></div>	
Air Bag	74%
Air Hanger	73%
Axle...	74%
Battery	68%
Brake...	70%
Electric...	71%
Landing...	82%
Mech Hanger...	73%
Steering...	77%
Trailer Kin...	89%
Truck...	61%
Truck Electric...	76%
Truck Kin...	64%
Truck Suspensio...	68%
Trailer Ai...	82%
Trailer...	70%

ALL CUSTOMERS.

Fleets Inspected Trend



PARAMETRIC PERFORMANCE

King Pin

88.08%

King Pin Bolts

89.40%

List Of Vehicles

Fault Details

Year	2022		2023	
FleetID	KingPin	KingPinBolt	KingPin	KingPinBolt
ALJ8784T	✓	✓		
ALK 7420T	✓	✓		
ALK 7431 T	✓	✓		
HESU 0004			✓	✓
HESU 0029			✓	✓
HESU 0043			✓	✓
STL 3664	✓	✓		
T 101BRZ	✓	✓		
T 118DPH	✓	✓		
T 134 DXS	✓	✓		
T 169 DUL	✓	✓		
T 175 DUL	✓	✓		
T 177AEG			✓	✓
T 184 DXS	✓	✓		
T 185 BDN	✓	✓		
T 206 CAF	✓	✓		
T 237 DPE			✓	✓
T 262 DFC	✓	✓		
T 287 DFJ	✓	✓		
T 289 DFJ	✓	✓		
T 304 DWA			✓	✓
T 419 CMH	✓	✓		
T 448 DAJ	✓	✓		
T 477 DAJ	✓	✓		
T 512DAJ	✓	✓		
T 515 DAJ	✓	✓		

FleetID
AIC 8923
ALJ 7186
ALJ8784T
ALK 6789
ALK 6790
ALK 7420T
ALK 7431 T
HESU 0001
HESU 0004
HESU 0029
HESU 0043
HESU 017
STL 3664
T 101BRZ
T 118DPH
T 120 BSS
T 134 DXS
T 169 DUL
T 175 DUL
T 177AEG
T 184 DXS
T 185 BDN
T 206 CAF
T 237 DPE
T 262 DFC

FleetID	KING PIN
T733BKE	WORN OUT
T831 CVZ	WORN OUT
T834CVZ	WORN OUT
T872DDM	DAMAGED

Air Bag

74%

Air Hanger

73%

Axle...

74%

Battery

68%

Brake...

70%

Electric...

71%

Landing...

82%

Mech Hanger...

73%

Steering...

77%

Trailer Kin...

89%

Truck...

61%

Truck Electric...

76%

Truck Kin...

64%

Truck Suspensio...

68%

Trailer Air System


82%

Trailer...

70%

ALL CUSTOMERS.

Fleets Inspected Trend



Brake Lining

54.32%

Calliper

30.86%

Brake Disc

25.93%

Brake Drum

59.26%

Brake Chamber

90.12%

Air Tank

62.96%

Air Pipes

76.54%

Brake Pad

25.93%

Slack Adjustment

91.36%

Valves

95.06%

PARAMETRIC PERFORMANCE

List Of Vehicles

FleetID

AIC 8923

ALJ 7186

ALJ8784T

ALK 6789

ALK 6790

ALK 7420T

ALK 7431 T

HESU 0001

HESU 0004

HESU 0029

HESU 0043

HESU 017

STL 3664

T 101BRZ

T 118DPH

T 120 BSS

T 134 DXS

T 169 DUL

T 175 DUL

T 177AEG

Fault Details

FleetID

BRAKE DISC

T 641DVH

DAMAGED

T133CCU

DAMAGED

T593DVZ

DAMAGED

T632CUB

DAMAGED

T799DVE

DAMAGED

T979CVJ

DAMAGED

Year

2022

FleetID

Air Pipes

Air Tank

Brake Chamber

Brake Disc

Brake drum

Brake Lining

Brake Pad

Calliper

Slack Adjuster

Valves

ALJ 7186

✓

✓

✓

✓

✗

✗

✓

✓

✓

✓

ALK 6789

✓

✓

✓

✓

✗

✗

✓

✓

✓

✓

ALK 6790

✓

✓

✓

✓

✗

✗

✓

✓

✓

✓

T 120 BSS

✓

✓

✓

✗

✗

✗

✗

✓

✓

✓

T 361 CGK

✗

✓

✓

✗

✓

✓

✗

✗

✓

✓

T 384 DVB

✓

✓

✓

✗

✓

✓

✗

✗

✓

✓

T 386 DVB

✓

✓

✓

✓

✓

✓

✓

✗

✓

✓

T 460 DSZ

✓

✓

✓

✓

✗

✗

✓

✓

✓

✓

T 469 DVT

✓

✓

✓

✗

✓

✓

✗

✗

✓

✓

T 508 CYV

T 568 CRA

✓

✓

✓

✓

✗

✗

✓

✓

✓

✓

T 625 DVW

T 641DVH

✓

✗

✓

✗

✗

✗

✗

✗

✓

✓

T 645 DNY

✓

✓

✓

✓

✗

✗

✗

✓

✓

✓

T 668DYY

✗

✓

✓

✗

✓

✓

✗

✗

✓

✓

T 686 DYY

✓

✓

✓

✗

✓

✓

✗

✗

✓

✓

T 725 CRT

✓

✓

✗

✓

✗

✗

✓

✓

✓

✓

T 976DVN

✗

✓

✓

✗

✓

✓

✗

✗

✓

✓

T112DNU

✓

✗

✓

✗

✓

✓

✗

✗

✓

✓

T133CCU

✗

✗

✓

✗

✗

✗

✗

✗

✓

✗

<

>

SUPERDOLL

Air Bag

74%

Air Hanger

73%

Axle...

74%

Battery

68%

Brake...

70%

Electric...

71%

Landing...

82%

Mech Hanger...

73%

Steering...

77%

Trailer Kin...

89%

Truck...

61%

Truck Electric...

76%

Truck Kin...

64%

Truck Suspensio...

68%

Trailer Ai...

82%

Trailer...

70%

ALL CUSTOMERS.

Fleets Inspected Trend

Lock Jaw

71.59%

Lock Bar

72.73%

Fifth Wheel Condition

65.91%

Fifth Wheel Bearing Repar Kit

48.86%

Fifth Wheel Repair Kit

61.36%

PARAMETRIC PERFORMANCE

List Of Vehicles

Year	2022				
FleetID	First 5BearingRepairKit Tracker	First 5RepairKit Tracker	First 5wheelCondition Tracker	First LockBar Tracker	Firs
AIC 8923	✓	✓	✓	✓	✓
ALJ 7186	✓	✓	✓	✓	✓
ALK 6789	✓	✓	✓	✓	✓
ALK 6790	✓	✗	✓	✓	✓
T 120 BSS	✓	✓	✓	✓	✓
T 361 CGK	✓	✓	✓	✓	✓
T 384 DVB	✗	✓	✓	✓	✓
T 386 DVB	✗	✓	✓	✓	✓
T 430 DLD	✗	✗	✗	✗	✗
T 434 DLD	✗	✗	✗	✗	✗
T 508 CYV					
T 522BMC	✗	✓	✓	✓	✓
T 533 AFP	✗	✗	✗	✗	✗
T 568 CRA	✓	✓	✓	✓	✓
T 625 DVW					
T 641DVH	✗	✗	✗	✗	✗
T 642 DNG	✗	✗	✗	✗	✗
T 645 DNY	✓	✓	✓	✓	✓
T 677 DHY	✓	✓	✓	✓	✓
T 693 DHY	✗	✗	✗	✗	✗
T 768 DNM	✗	✗	✗	✗	✗
T 775 DNM	✗	✗	✗	✗	✗
T 776 DNM	✗	✗	✗	✗	✗

FleetID

AIC 8923

ALJ 7186

ALJ8784T

ALK 6789

ALK 6790

ALK 7420T

ALK 7431 T

HESU 0001

HESU 0004

HESU 0029

HESU 0043

HESU 017

STL 3664

T 101BRZ

T 118DPH

T 120 BSS

T 134 DXS

T 169 DUL

T 175 DUL

T 177AEG

T 184 DXS

T 185 BDN

T 206 CAF

Fault Details

VehicleID	5TH WHEEL BEARING REPAIR
T 384 DVB	WORN OUT
T 386 DVB	WORN OUT
T 522BMC	WORN OUT
T 533 AFP	WORN OUT
T 641DVH	WORN OUT
T 768 DNM	WORN OUT
T 911DMR	WORN OUT
T 976DVN	WORN OUT
T103 ARN	WORN OUT
T205DGP	WORN OUT
T223DSH	WORN OUT
T233DMF	WORN OUT
T264CZB	WORN OUT
T279CZA	WORN OUT
T331DYQ	WORN OUT
T338DPX	WORN OUT
T390DEP	WORN OUT
T411DFU	WORN OUT
T504 CGT	WORN OUT
T506CPH	WORN OUT
T521DSN	WORN OUT
T535DAS	WORN OUT
T564DNP	WORN OUT
T 206 CAF	WORN OUT

SUPERDOLL

