■■■■ ■■■■■ • GOVERNMENT OF INDIA

■■ ■■■■■ ■■■■■■■■ • MINISTRY OF JAL SHAKTI

■■■■■■■■■ ■■■■ ■■■■■■■ ■■■■■■■■■■ • NATIONAL DAM SAFETY AUTHORITY

STATUTORY DAM SAFETY INSPECTION & CONDITION REPORT

File Ref: F.No. NDSA/CWC/2026/INSP/AUDIT-0842 | Verification Code:
REP-HV-BHK-TEST-1788962332-20260910_043738

OFFICIAL STATUTORY RECORD **DAM SAFETY ACT 2021 COMPLIANT** **SCAN QR TO VERIFY AUTHENTICITY**

Dam Name:	Bhakra Hydro Project	**Dam Asset Code:**	BHK-TEST-1788962332
Location & State:	Bilaspur, Himachal Pradesh	**Structural Type:**	Concrete Gravity
Height & Coordinates:	226.0 m (31.41° N, 76.43° E)	**Issuing Department:**	National Dam Safety Authority (NDSA)
Inspecting Body:	Hydroelectric Structural Inspection Cell	**Audit Timestamp:**	10 September 2026, 04:37 UTC

1. STRUCTURAL ANOMALY & DEFECT ASSESSMENT SUMMARY

DEF-TEST-117	CRACK	**DefectSeverity.HIGH**	65.5 mm	WORK_ORDER_CREATED

2. RECORDED INSPECTIONS & FIELD VISITS HISTORY

Insp Code	Type & Date	Inspector / Department	Status
INSP-BHK-TEST-1788962332-20260909358	**DRONE_VISUAL** 2026-09-09	Hydroelectric Structural Inspection Cell	**InspectionStatus.DATA_UPLOADED**

3. SANCTIONED WORKS & MAINTENANCE HISTORY

WO-2026-004	**Inject polyurethane resin & epoxy seal**	Priority: **HIGH**	**MaintenanceStatus.OPEN**

Prepared By:
Senior Inspection Engineer
Hydroelectric Inspection Cell

Reviewed By:
Executive Engineer
Dam Safety Organisation (SDSO)

Approved By Authority:
Chief Engineer (Dam Safety)
Ministry of Jal Shakti / CWC

GOVT OF INDIA
NDSA • CWC
STATUTORY AUDIT
OFFICIAL SEAL