■■■■ ■■■■■ • GOVERNMENT OF INDIA

■■ ■■■■■ ■■■■■■■■ • MINISTRY OF JAL SHAKTI

■■■■■■■■■ ■■■■ ■■■■■■■ ■■■■■■■■■■ • NATIONAL DAM SAFETY AUTHORITY

STATUTORY DAM SAFETY INSPECTION & CONDITION REPORT

File Ref: F.No. NDSA/CWC/2026/INSP/AUDIT-0842 | Verification Code:
REP-HV-HKD-01-20261005_155500

OFFICIAL STATUTORY RECORD **DAM SAFETY ACT 2021 COMPLIANT** **SCAN QR TO VERIFY AUTHENTICITY**

Dam Name:	HiraKud Dam	**Dam Asset Code:**	HKD-01
Location & State:	Sambalpur, Odisha	**Structural Type:**	Embankment
Height & Coordinates:	61.0 m (21.57° N, 83.87° E)	**Issuing Department:**	National Dam Safety Authority (NDSA)
Inspecting Body:	Hydroelectric Structural Inspection Cell	**Audit Timestamp:**	05 October 2026, 15:55 UTC

1. STRUCTURAL ANOMALY & DEFECT ASSESSMENT SUMMARY

DEF-010-176	SEEPAGE	DefectSeverity.MEDIUM	345.6 mm	VERIFIED
DEF-010-127	CRACK	DefectSeverity.MEDIUM	50.0 mm	VERIFIED
DEF-010-128	CRACK	DefectSeverity.MEDIUM	46.4 mm	VERIFIED
DEF-010-129	SEEPAGE	DefectSeverity.MEDIUM	210.2 mm	VERIFIED
DEF-010-130	CRACK	DefectSeverity.MEDIUM	109.4 mm	VERIFIED
DEF-010-138	SEEPAGE	DefectSeverity.MEDIUM	140.0 mm	VERIFIED
DEF-010-165	CRACK	DefectSeverity.MEDIUM	41.9 mm	VERIFIED

2. RECORDED INSPECTIONS & FIELD VISITS HISTORY

Insp Code	Type & Date	Inspector / Department	Status
INSP-HKD-01-20260 9241248	**DRONE_VISUAL** 2026-09-24	Hydroelectric Structural Inspection Cell	InspectionStatus.COMPLETED

3. SANCTIONED WORKS & MAINTENANCE HISTORY

WO-2026-003	**Immediate work needed**	Priority: **HIGH**	**MaintenanceStatus.CLOSED**

Prepared By:
Senior Inspection Engineer
Hydroelectric Inspection Cell

Reviewed By:
Executive Engineer
Dam Safety Organisation (SDSO)

Approved By Authority:
Chief Engineer (Dam Safety)
Ministry of Jal Shakti / CWC

GOVT OF INDIA
NDSA • CWC
STATUTORY AUDIT
OFFICIAL SEAL