■■■■ ■■■■■ • GOVERNMENT OF INDIA

■■ ■■■■■ ■■■■■■■■ • MINISTRY OF JAL SHAKTI

■■■■■■■■■ ■■■■ ■■■■■■■ ■■■■■■■■■■ • NATIONAL DAM SAFETY AUTHORITY

STATUTORY DAM SAFETY INSPECTION & CONDITION REPORT

File Ref: F.No. NDSA/CWC/2026/INSP/AUDIT-0842 | Verification Code:
REP-HV-THR-RBAC-1788945544-20260910_043730

OFFICIAL STATUTORY RECORD **DAM SAFETY ACT 2021 COMPLIANT** **SCAN QR TO VERIFY AUTHENTICITY**

Dam Name:	Tehri Hydroelectric Dam	**Dam Asset Code:**	THR-RBAC-1788945544
Location & State:	Tehri Garhwal, Uttarakhand	**Structural Type:**	Rockfill
Height & Coordinates:	260.5 m (30.37° N, 78.48° E)	**Issuing Department:**	National Dam Safety Authority (NDSA)
Inspecting Body:	Hydroelectric Structural Inspection Cell	**Audit Timestamp:**	10 September 2026, 04:37 UTC

1. STRUCTURAL ANOMALY & DEFECT ASSESSMENT SUMMARY

DEF-NONE	No structural defects recorded	HEALTHY	0 mm	NORMAL

2. RECORDED INSPECTIONS & FIELD VISITS HISTORY

Insp Code	Type & Date	Inspector / Department	Status
—	No prior field visits recorded for this dam	—	—

3. SANCTIONED WORKS & MAINTENANCE HISTORY

—	No maintenance work orders recorded for this dam	—	—

Prepared By:
Senior Inspection Engineer
Hydroelectric Inspection Cell

Reviewed By:
Executive Engineer
Dam Safety Organisation (SDSO)

Approved By Authority:
Chief Engineer (Dam Safety)
Ministry of Jal Shakti / CWC

GOVT OF INDIA
NDSA • CWC
STATUTORY AUDIT
OFFICIAL SEAL