

Building Compliance Inspection Report

Client: Demo data - privacy protected · Permit and compliance inspection
Visit Date: 28 September 2026, 10:15 AM – 11:25 AM
Generated by: AI report assistant, from a Preserver field export

Summary

A building compliance inspection was carried out at the property, covering an exterior facade condition check, a fire safety and emergency signage check, and a permit plan comparison against as-built works. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The building facade was found in good condition with no defects noted, emergency exit signage was confirmed operational and correctly positioned, and the completed works were consistent with the approved permit plans.

Inspection Summary

Category	Observation	Status	Action Required
Facade Condition	Good condition, no defects noted	Complete	None
Fire Safety Signage	Exit signage operational, correctly positioned	Complete	None
Permit Plan Check	As-built works consistent with approved plans	Complete	Issue compliance certificate

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Building facade — exterior condition check

-27.4756, 153.0289 · 28 Sep 2026, 10:22 AM


Exterior building facade inspected, found in good condition with no defects noted.



Fire safety — emergency exit signage

-27.4756, 153.0289 · 28 Sep 2026, 10:48 AM

Emergency exit signage checked, confirmed operational and correctly positioned.



Permit plans — as-built comparison

-27.4756, 153.0289 · 28 Sep 2026, 11:12 AM

Approved permit plans compared against completed works, confirmed consistent.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
10:22 AM	Voice	"Facade's in good shape, nothing to flag on the exterior condition this visit."
10:48 AM	Voice	"Exit signage's all lit and positioned correctly, that's a pass on fire safety."
11:12 AM	Text	As-built works compared against the approved permit plans, confirmed consistent.

Site Visit Log

10:15 AM	Activity started on-site — GPS lock confirmed, property location
10:22 AM	Facade condition check — photo + voice observation logged
10:48 AM	Fire safety signage check — photo + voice observation logged
11:12 AM	Permit plan comparison — photo + text observation logged
11:25 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a council-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me