

Pool Barrier Compliance Report

Client: Demo data - privacy protected · Pool safety compliance inspection

Visit Date: 28 September 2026, 11:00 AM – 11:55 AM

Generated by: AI report assistant, from a Preserver field export

Summary

A pool safety compliance inspection was carried out at the property, covering a self-closing gate latch check, a pool area and barrier condition check, and a fence height measurement against the required standard. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The self-closing gate latch was tested and confirmed operational, the pool area and barrier were found in good condition with no gaps or climbable objects, and the fence height was measured and confirmed compliant with the required standard.

Inspection Summary

Category	Observation	Status	Action Required
Gate Latch	Self-closing, tested and operational	Pass	None
Barrier Condition	No gaps or climbable objects found	Pass	None
Fence Height	Measured, compliant with required standard	Pass	Issue compliance certificate

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Gate latch — self-closing mechanism check

-27.4715, 153.0243 · 28 Sep 2026, 11:06 AM

Self-closing gate latch tested, confirmed operational and self-latching.



Pool area — barrier condition check

-27.4715, 153.0243 · 28 Sep 2026, 11:22 AM

Pool area and barrier inspected, found in good condition with no gaps or climbable objects.



Fence height — compliance measurement

-27.4715, 153.0243 · 28 Sep 2026, 11:40 AM

Fence height measured, confirmed compliant with the required minimum standard.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
11:06 AM	Voice	"Gate latch is self-closing and testing fine, latches every time without fail."
11:22 AM	Voice	"Barrier's in good condition, no gaps and nothing nearby someone could climb on."
11:40 AM	Text	Fence height measured and confirmed compliant with the required standard.

Site Visit Log

11:00 AM	Activity started on-site — GPS lock confirmed, property location
11:06 AM	Gate latch check — photo + voice observation logged
11:22 AM	Barrier condition check — photo + voice observation logged
11:40 AM	Fence height measurement — photo + text observation logged
11:55 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a compliance-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me