

Wellsite Safety Inspection Report

Client: Demo data - privacy protected · Wellsite compliance walk
Visit Date: 28 September 2026, 6:00 AM – 7:15 AM
Generated by: AI report assistant, from a Preserver field export

Summary

A wellsite safety inspection was carried out at the facility, covering a pipeline valve station check, a gas leak detection scan, and a wellhead safety and PPE inspection. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The valve station pressure gauges were within normal operating range, the gas leak detector scan returned no readings across the checked joints, and the wellhead area was confirmed compliant with PPE and safety signage in place.

Inspection Summary

Category	Observation	Status	Action Required
Valve Station	Pressure gauges within normal operating range	On Track	None
Gas Leak Detection	No readings detected across checked joints	Complete	None
Wellhead & PPE	Compliant, safety signage in place	Complete	None

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Valve station — pressure check

-23.6789, 149.2345 · 28 Sep 2026, 6:10 AM

Pipeline valve station and pressure gauges checked, readings within normal operating range.



Pipe joint — gas leak detection scan

-23.6792, 149.2349 · 28 Sep 2026, 6:42 AM

Handheld gas leak detector used to scan pipe joints, no readings returned.



Wellhead — safety and PPE inspection

-23.6795, 149.2352 · 28 Sep 2026, 7:05 AM

Wellhead area inspected for safety compliance, PPE and signage confirmed in place.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
6:10 AM	Voice	"Valve station's reading normal this morning, pressure's steady across the gauges."
6:42 AM	Voice	"Ran the gas detector over the joints on this section, no readings, all clear."
7:05 AM	Text	Wellhead area inspected, PPE and safety signage confirmed compliant.

Site Visit Log

6:00 AM	Activity started on-site — GPS lock confirmed, wellsite location
6:10 AM	Valve station check — photo + voice observation logged
6:42 AM	Gas leak detection scan — photo + voice observation logged
7:05 AM	Wellhead safety inspection — photo + text observation logged
7:15 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a compliance-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me