

Asbestos Assessment Report

Client: Demo data - privacy protected · Pre-renovation asbestos assessment

Visit Date: 28 September 2026, 8:30 AM – 9:40 AM

Generated by: AI report assistant, from a Preserver field export

Summary

An asbestos assessment was carried out at the property, covering a suspected material identification check, a roof sheeting condition check, and an exclusion zone sign-off. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

Suspected materials were identified and flagged for laboratory sampling, roof sheeting was found in stable, non-friable condition with no visible damage, and the exclusion zone was set up and signed off before works could proceed.

Assessment Summary

Category	Observation	Status	Action Required
Material Identification	Suspected material flagged for sampling	Complete	Send sample to laboratory
Roof Sheeting Condition	Stable, non-friable, no visible damage	Complete	None
Exclusion Zone	Set up and signed off before works	Complete	None

Field Evidence


The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Suspected material — identification check

-27.4683, 153.0221 · 28 Sep 2026, 8:36 AM

Suspected material identified and flagged for laboratory sampling.



Roof sheeting — condition check

-27.4683, 153.0221 · 28 Sep 2026, 9:02 AM

Roof sheeting inspected, found stable and non-friable with no visible damage.



Exclusion zone — sign-off

-27.4683, 153.0221 · 28 Sep 2026, 9:28 AM

Exclusion zone set up and signed off before works could proceed.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
8:36 AM	Voice	"Got a suspected material here, flagging it for lab sampling before we go any further."
9:02 AM	Voice	"Roof sheeting's stable, non-friable, no visible damage on this section."
9:28 AM	Text	Exclusion zone set up and signed off before works could proceed.

Site Visit Log

8:30 AM	Activity started on-site — GPS lock confirmed, property location
8:36 AM	Material identification check — photo + voice observation logged
9:02 AM	Roof sheeting condition check — photo + voice observation logged
9:28 AM	Exclusion zone sign-off — photo + text observation logged
9:40 AM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the assessment, turned into a compliance-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me